

ASS. REC-BY: Tup

REF: CS/CX/23000310/Tups

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$64K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WY

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLV 2274E Yr Regn: 20171 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Astra ST1.0 C.D. 991

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 61838 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WOLKE8EAOH18085895

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 77

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.L. 11/1/23

Survey held at B. first

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass 40?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) \_\_\_\_\_

Rep. Format: \_\_\_\_\_

Lump Sum / L.B.K. / P

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

**Repair Estimate**

Vehicle number: SLV2274E

Make &amp; Model: Opel Astra

Chassis number: W0LBE8EA0H8085895

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
p	Bonnet	1	\$ x 2,040.00
2	Bonnet RH hinge	1	\$ x 188.00
3	Bonnet LH hinge	1	\$ x 188.00
4	Bonnet lock	1	\$ x 178.00
5	Front bumper	1	\$ del 1,941.00
6	Front bumper clips	1set	\$ new 80 80.00
7	Front bumper RH side retainer	1	\$ x 144.00
8	Front bumper LH side retainer	1	\$ x 144.00
9	Front bumper RH LED lamp	1	\$ x 424.00
10	Front bumper RH LED lamp cover garnish	1	\$ x 162.00
11	Front bumper lower grille	1	\$ x 453.00
12	Front bumper lower spoiler	1	\$ x 558.00
13	Front bumper reinforcement	1	\$ x 784.00
14	Front RH fender	1	\$ BA 663.00
15	Front RH fender emblem	1	\$ x 74.00
16	Front RH fender splash shield	1	\$ x 209.00
17	Front RH fender splash shield clips	1set	\$ x 70.00
18	RH headlamp	1	\$ cut 3,904.00
19	RH headlamp halogen	1	\$ x 913.00
20	RH front sport rim	1	\$ cut 1,095.00
21	RH front shock absorber	1	\$ x 389.00
22	RH front lower arm	1	\$ x 732.00
23	RH front knuckle arm	1	\$ x 616.00
24	RH front wheel bearing	1	\$ x 375.00
25	RH front tie rod end	1	\$ x 143.00
26	Support panel	1	\$ x 922.00

\$ 17,389.00

Parts less 10% \$ 3,477.80



Total \$ 13,911.20

No.	Special Nett Items	Qty	Amount S\$
1	RH front tyre	1	\$ 550.00
2	Brake fluid	1	\$ 80.00

Total: \$ 630.00

No.	Labour and painting		Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	300	\$ 1,400.00
2	Spray painting on affected areas and panels	400	\$ 1,200.00
3	Check wiring and lighting system on affected areas	30	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	30	\$ 80.00
5	Remove and reinstall aircon condenser, pipes and hoses to assist repair	X	\$ 200.00
5	Remove and reinstall radiator assy, hoses and fan assy to assist repair	X	\$ 200.00
6	Test drive and adjust wheel alignment system	80	\$ 180.00
7	Remove and replace front undercarriage parts to assist repair	X	\$ 450.00

Total: \$ 3,790.00

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)

Working days: \_\_\_\_\_

Tan Jiah 97445749  
 up 11/12/2012 12:30pm  
 c/s Meru after repair  
 Tan Jiah @ 11/12/2012 12:30pm  
 3 days  
 - To check work's done of accident  
 - To check part price

Spare Parts: \$ 13,911.20

Special Nett \$ 630.00

Labour: \$ 3,790.00

**Total Amount: \$ 18,331.20**

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - If any item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Date:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	870G
<b>Vehicle Details</b>	
Vehicle No.:	SLV2274E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Jan 2023
Vehicle Make:	OPEL
Vehicle Model:	ASTRA ST 1.0 AT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	B1171027HRXX0489
Chassis No.:	W0LBE8EA0H8085895
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$20,179.00
Original Registration Date:	26 Dec 2017
First Registration Date:	26 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,251.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2027
PARF Rebate Amount:	\$3,675.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	25 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,200.00
COE Rebate Amount:	\$18,976.00
<b>Total Rebate Amount:</b>	<b>\$22,651.00</b>

The information contained herein is correct as at 06 Jan 2023

OK

\$64K

Date of Accident : 31/12/22 Accident Time: 1705pm (24-HR-FORMAT)  
Accident Place : Blk 248 Hougang Ave 3 carpark  
Vehicle Reg. No (Car plate No.) : SLV2274E CC: 150 Vehicle Make/Model: Opel Astra  
Insurance Company : Allianz Policy No. SP2000629175-01  
Name of Registered Owner : Company / Individual low luan kian  
ID of Registered Owner : Co Reg No: \_\_\_\_\_ Owner's NRIC No: S12318709  
OWNER EMAIL ADDRESS: currentests@gmail.com : Co Contact No: \_\_\_\_\_ Owner's Contact No: 91384803  
DRIVER'S Name : Teo Jiam Sheng DRIVER'S NRIC No: S8711924F  
DRIVER'S Date of Birth : 30/04/1987 DRIVER'S License Pass Date 21/07/2016  
Relationship bet. Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: \_\_\_\_\_  
DRIVER'S Address : 19B Lim tua tow road #01-03  
DRIVER'S Contact No./ Alt No. : 1) 96379129 2) \_\_\_\_\_  
DRIVER'S Occupation : INDOOR \ OUTDOOR (eg. working inside or outside of an ofc)  
Email Address : \_\_\_\_\_  
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
Number of Passengers (including Driver): 0 Name & Gender: 0  
Was the accident reported to the police? YES \ NO  
Was there any video Captured by car camera: YES \ NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
Any injuries, if yes(name of the injured person) no

**Other Party Driver's Particulars (if any)**

Vehicle Reg No: <u>SDR 80680</u>	Vehicle Reg No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name DRIVER: _____	Name DRIVER: _____
IC No. DRIVER: _____	IC No. DRIVER: _____
DRIVER'S Contact & add: _____	DRIVER'S Contact & add: _____

REPORT FORM EXPLAINED IN : ENGLISH / CHINESE / MALAY / TAMIL OTHERS: \_\_\_\_\_

WHO REPORTED THE ACCIDENT : OWNER / DRIVER / BOTH



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

### Sketch Plan


A2SLV2274BE  
36513R 30680  
B1K 248 Hougang Ave 3  
CAR PARK  
TANK


Describe Circumstance of the Accident

my vehicle was stationary at BIK 248 hougang  
Ave 3 carpark, I left my car there to do my own  
things, when i came back i saw a note and i  
realised vehicle (b) collided onto my vehicle

Declaration

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel