

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Reg. No: 199607198R GST Reg. No. 19-9607198-R | | | | | |
|---|---|--|-----------------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | Ref: | CS/AGI23000315/Tqy3m4 | |
| | | INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE | Date | e: 16/03/2023 | |
| | | | Cod | e: AGI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SJM 2395K | Veh. Inspected | SLA 3111X | |
| | Policy No. | P10298344R03 | Coverage (\$) | 0.00 | |
| | Claim No. | C10019733/JL | Excess (\$) | 0.00 | |
| | Assign From | MAYBIE CHUA | Assign Date | 10/01/2023 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HONDA VEZEL | c.c | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | 2016 | |
| | Chassis No. | RU11110414 | Colour | SILVER | |
| | Odometer | 69514 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm | |
| | L/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm | |
| | R/H Rear Tyre | 215/60 R16 | DUNLOP | 6 mm | |
| | L/H Rear Tyre | 215/60 R16 | DUNLOP | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 08/01/2023 | Inspection Date | 12/01/2023 | |
| | Survey held at HUP LEY HUAT MOTOR SPRAY PAINTING SVS | | | | |
| | BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883 | | | | |
| 5a. Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | 5b. Estimate Days of Repair | | | | |

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: