

ASS. REC. BY:

REF: C72/23000316/kn

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s

of

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8155k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 7-10 days

Res.: Yes or No

Lum Sum: 1.131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SME 162k

Yr Regn: 09.18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW

Colour: M. Blue

Sp. Reading: 68012

Eng/No: _____

C/No: WBA 2J52040VD72525

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: Pir

R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 6/1/23

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 10/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

S - RS. SI

F. Photos

Others

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Ching Motor Repair Shop

Blk 176 #02-08 Sin Ming Drive Sin Ming AutoCare
Singapore 575721 HP 91004390/91254449 Fax 6484 1482
Email : chingmotorrepair@gmail.com

Not Authorized
Phony B4 print
7-10 days

M/s China Taiping Insurance (S) Pte Ltd

DATE

07.01.2023

3 Anson Road #16-00 Spring leaf Tower

CAR NO

SME 162 K

Singapore 079909

MAKE

B M W

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SJN 8309 R

Pc	Pcs	WBA2J52040VD72525	UNIT PRICE	AMOUNT
1	pc	Rear boot <i>By ✓</i>		
2	pcs	Rear boot hinge (left & right) <i>R x</i>		
1	pc	Rear boot weather strip <i>DT/DA ✓</i>		
1	pc	Rear boot lock <i>Red ✓</i>		
1	pc	Rear boot lock striker <i>R x</i>		
1	pc	Rear boot insulator <i>R x</i>		
1	pc	Rear boot inner top board cover <i>?</i>		
1	pc	Rear boot top spoiler <i>?</i>		
1	pc	"BMW" emblem <i>New ✓</i>		
1	pc	"M24Di" emblem <i>New ✓</i>		
2	pcs	Tail lamp (left & right) <i>CR ✓</i>		
1	pc	Rear bumper <i>BT ✓</i>		
10	pcs	Rear bumper clips <i>New ✓</i>		
1	pc	Rear bumper sponge <i>?</i>		
2	pcs	Rear bumper stay (left & right) <i>?</i>		
2	pcs	Rear bumper side retainer (left & right) <i>DT ✓</i>		
2	pcs	Rear bumper reverse sensor <i>DT ✓</i>		
1	pc	Rear bumper lower lip <i>BT ✓</i>		
1	pc	Rear bumper tow cover <i>DT ✓</i>		
2	pcs	Rear bumper lamp (left & right) <i>DT/DA o/s mt ✓</i>		
1	pc	Rear bumper inner beam <i>BR ✓</i>		
1	pc	Rear bumper upper guide <i>?</i>		
1	pc	Rear bumper lower guide <i>?</i>		
1	pc	Rear end panel <i>?</i>		
1	pc	Rear end panel top garnish <i>Red ✓</i>		
8	pcs	Rear end panel top garnish clips <i>New ✓</i>		
1	pc	Rear spare tyre tank panel <i>?</i>		
1	pc	Rear spare tyre panel cover board <i>?</i>		
3	pcs	Rear spare tyre panel heat shield (left & right) <i>?</i>		
1	pc	Rear number plate with casing <i>R x</i>		
2	pcs	Rear exhaust box <i>?</i>		
2	pcs	Rear exhaust pipe <i>?</i>		
1	pc	Keyless sensor <i>?</i>		
1	pc	Keyless kick module <i>?</i>		
Page 1 of 3				Total

Susan Lim

Ching Motor Repair Shop.

Ching Motor Repair Shop

Blk 176 #02-08 Sin Ming Drive Sin Ming AutoCare
Singapore 575721 HP 91004390/91254449 Fax 6484 1482
Email : chingmotorrepair@gmail.com

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00 Spring leaf Tower

Singapore 079909

DATE

07.01.2023

CAR NO

SME 162 K

MAKE

B M W

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SJN 8309 R

WBA2J52040VD72525

Continue from page one.

Pc	Pcs	
1	pc	Front bumper
1	pc	Front bumper sponge
1	pc	Front bumper reinforcement
2	pcs	Front bumper bracket (LH & RH)
2	pcs	Front bumper side retainer (LH & RH)
2	pcs	Front bumper centre chrome grille
1	pc	Front bumper tow cover
1	pc	Front bumper "BMW" logo
2	pcs	Front bumper sensor
1	pc	Front number plate with casing
2	pcs	Front head lamp (LH & RH)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Susan Lim

Ching Motor Repair Shop.

Page 2 of 3

Total

Blk 176 #02-08 Sin Ming Drive Sin Ming AutoCare
Singapore 575721 HP 91004390/91254449 Fax 6484 1482
Email : chingmotorrepair@gmail.com

DATE 07.01.2023

CAR NO SME 162 K

MAKE BMW

Pc	Pcs	WBA2J52040VD72525		
			UNIT PRICE	AMOUNT
		Continue from page two.		

Susan Lim

SA1823170001 / Abwin Service Pte Ltd
ENTRY DATE & TIME: 07/01/2023 10:43 (SGT)
SUBMITTED BY: Claims
VERSION: 1 (07/01/2023 10:43 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission _____ 07/01/2023 10:43 (SGT)
Reported by _____ Both
Date of Accident _____ 06/01/2023 19:20 (SGT)
Exact Location of Accident _____ PIE, Singapore
Additional Location Information _____ PIE TOWARDS CHANGI (AFTER SIMS AVE EXIT)
Country/State of Loss _____ Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number _____ SME162K

INSURED/POLICYHOLDER

Is company? _____ No
Name Of Registered Owner _____ WUN WEN-NA
NRIC No _____ SXXXX148G
Email Address _____ WENNA.WUN@GMAIL.COM
Mobile Phone No _____ (Phone) +65-90703231
Alternative Phone No _____ -

VEHICLE PARTICULARS

Manufacturer _____ BMW
Model _____ M240i
Variant _____ -
Exact purpose for which vehicle was being used at time of accident _____ Private use
Are you claiming under your own insurance policy for repair to your vehicle? _____ No - Claiming third party
Vehicle Category _____ Private car
Transmission _____ Auto
CC _____ 2998

INSURANCE COMPANY

Name of Insurance Company _____ Liberty Insurance Pte Ltd
Policy Number / Cover Note Number _____ S122V11148/VPS/R02

DRIVER

Name of Driver _____ WUN WEN-NA
NRIC No _____ SXXXX148G
Date Of Birth _____ 23/11/1969
Occupation _____ Indoor

IMPORTANT NOTICE

- 8. Consent under the Personal Data Protection Act (PDPA)**

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

providers or agents
es.

Q

ABWIN SERVICE PTE LTD
Co. Reg. No.
201318885G

Responsible Officer

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Vehicle A: SME 162 K

Vehicle B: SJN 8309 R

Vehicle C: SJS 1502 R