

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	GREAT AMERICAN	N INSURANCE COMPANY	Ref:	CS/GAI23000317/Uvy3e2	
	3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 0391	AL TOWER	Date:	17/01/2023	
			Code:	GAI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMS 2299M	Veh. Inspected	SLL 9689Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CLMOMVP000001287	Excess (\$)	0.00	
	Assign From	SHERY WONG	Assign Date	10/01/2023	
2. Vehicle Particulars & Condition					
	Make & Model	SUBARU XV (A)	c.c	1600	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JF1GP3KC5HG201079	Colour	WHITE	
	Odometer	80250 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/55Z R17	ROYAL PERFORMANCE	6 mm	
	L/H Front Tyre	225/55Z R17	ROYAL PERFORMANCE	6 mm	
	R/H Rear Tyre	225/55Z R17	ROYAL PERFORMANCE	6 mm	
	L/H Rear Tyre	225/55Z R17	ROYAL PERFORMANCE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/01/2023	Inspection Date	10/01/2023	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			