ASS. REC. BY:	REF:	CTI		LOKE	45		
N		SIGNMEN	T	*			
From:	Dale:	Veh No:	SHA 5154 G	Yr Regn: (/	FEB 12019		
Estimated Cost:		Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /					
OD / TP / WS / TP RES / OD RES / EVA / INV / MV		Truck / Trailer or					
		Make:	HYWDAI TONI	d 62 c	c 1, 180		
		Colour	BLYE		d)Std/NI/NA		
		- Co Doeding			ed / Std / NI / NA		
of	-	300 311					
Insured:	Eng/No:	CNO: KMHC857CVKU13.3567					
Claire No	Policy No.			Gen. Cond: Good / Fair / Poor / Burnt			
	Sum Insured: Excess:			Steering: (norder / Jammed / Leaked / Burnt or			
	(Client's Record)			Brake: Inorder/ Jammed / Leaked / Burnt or			
Make of Veh:		Modi: Nii	SIRIM I STD AIRIM	or			
	Υ΄	Tyre Size:	F: 195	165RIS			
(Policy Condition)	Tyre Size: F: (95/65 R15						
Remark: The veh had comm	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /						
repair at the time o	f inspection.	TOYO / YOK	O or LEST	AKE .			
Bal. or Market Value:	Bal. or Market Value:			Rear			
IDAC Accident Rport:	IDAC Accident Rport: Consistent? : Yes or No			R/Bal.	4 mm		
GIA / PR Seen:	L/Bal.	4 mm	L/Bal.	4 mm			
Est. Repairs: 2	D.O.A. 5/1/2023 D.O.I. 6/1/2023						
Lum Sum:	% 3 Val.: Yes or No	Survey held at	(DG	E COYANG			
CA / REV / REP. / 24	HRS	Des. of Damag	es: Frt / Rear / O/S	I N/S I U/C I Roc	oftop or		
	Vehicle: IN/OUT			N/S FRT			
Dale: Person	Contacled:	The U/C /	Chassis frame / Body	Structure affected			
Date / Time Action / Instru	uction				CT LIS		
					r annagang-agus recordes tribata <b>agusta t</b> erri p <b>ag</b> an <del>n at</del> ri		
				***************************************			
				,			
Date/Time, File Pass 107	reli. Report Da	ys Of Repail	r:				
1) : F	survey No. o	of Trip:	Survey Fee:				
Dale/Time, File Return to?		Transportation:					
2)	Add Fee:	: Site Insp	, (\$	_)S+RS,SI			
	Ĭ	: Interview	, (\$	) Photos			
Report Format:	ř	: Tech. In	vs (\$	) Others			
_ump Sum / I.B.I: (\$	)	: Weeken	d (\$	)			
to pulpormulai discommin		<del></del>		TOTAL			

(96/11 1

REF: