

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA5154G

Make : HYUNDAI

Model : IONIQ(G2)

Date: 06/01/2023

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	FRT BUMPER COVER			\$ 481.10	/CRA
10	FRT BUMPER CLIPS			\$ 22.00	/NEC
1	FRT BUMPER SIDE BRACKER LH			\$ 28.00	?
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50	/SCR
1	HEADLAMP LH			\$ 2,110.30	/SCR
1	FRT BUMPER SIDE MOULDING LH			\$ 93.60	/SCR
1	FRT BUMPER LWR GRILLE MOULDING			\$ 186.90	/SCR
1	DAYLIGHT LH			\$ 642.50	/SCR
	SUB TOTAL			\$ 3,932.90	
	LESS 20%			\$ 786.58	
	DISCOUNTED TOTAL			\$ 3,146.32	
				\$ -	
	Labour Charge				
	PANEL BEATING			\$ 400.00	250
	SPRAY PAINTING CHARGE			\$ 300.00	250
	CHECK ALL LIGHTING			\$ 60.00	30
	TOTAL LABOUR			\$ 760.00	
	ESTIMATE TOTAL			\$ 3,906.32	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKE

6/1/2023 1625

L/S

2 Days

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS