

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/LIP23000355/Uvy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBU 150Rat Workshop m/s Son Hu mhu-

of _____

Insured: GBB5733B

Policy No. _____

Claims No. IVS23/0079

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 18k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 4279Date: _____ Person Contacted: LTA 10373

Vehicle: IN/OUT

Veh No: FBU 150R Yr Regn: 22/07/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Nmax c.c. 155Colour: Black A/C: Insured / Std / NI / NASp.Reading: 9997 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3SG568NK133571Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 110-70-13R: 80-70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or IRCFront 7 mm Rear 7 mmR/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 27/12/22 D.O.I. 11/1/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/5/23 Submit report motorcycle hasn't send in for repair

19/5/23

Submit preli report-revised fig \$230 check items \$685.80

The vehicle has not send in for repair

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 19/5/23-typist

Days Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	847J
Vehicle Details	
Vehicle No.:	FBU150R
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jan 2023
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX 155 ABS CVT
Primary Colour:	Black
Manufacturing Year:	2022
Engine No.:	G3L8E1040979
Chassis No.:	MH3SG5680NK133571
Maximum Power Output:	-
Open Market Value:	\$3,163.00
Original Registration Date:	22 Jul 2022
First Registration Date:	22 Jul 2022
Transfer Count:	1
Actual ARF Paid:	\$475.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2032
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$10,889.00
COE Rebate Amount:	\$10,373.00
Total Rebate Amount:	\$10,373.00

The information contained herein is correct as at 11 Jan 2023

OK



Singapore Tattoo Artist

Walk-in without booking. Get your dreamed tattoo sooner in Singapore
SgShadowTattoo

[Contact Us](#)

Bike model
 Type Of Vehicle
 Price From
 Price To
 Class

[More Search Options](#)

Sort By

Sort By



Yamaha Nmax 155

Reg Date : 20/05/2021

Capacity : 155cc

Vehicle Type : Scooters

Mileage : -

SGD \$15000

Posted on : 27/12/2022

★ Paid Ad

★ Dealer Ad

[Details >](#)


Yamaha Nmax 155

Reg Date : 13/04/2021

Capacity : 155cc

Vehicle Type : Scooters

Mileage : 48000km

SGD \$14588

Posted on : 09/01/2023

★ Paid Ad

★ Dealer Ad

[Details >](#)


Yamaha Nmax 155

Reg Date : 20/04/2022

Capacity : 155cc

Vehicle Type : Scooters

Mileage : -

SGD \$16000

Posted on : 03/01/2023

★ Paid Ad

★ Dealer Ad

[Details >](#)


Yamaha Nmax 155

Reg Date : 31/01/2020

Capacity : 155cc

Vehicle Type : Scooters

Mileage : 99753km

SGD \$11888

Posted on : 09/12/2022

★ Paid Ad

★ Dealer Ad

[Details >](#)


Yamaha Nmax 155

Reg Date : 11/12/2020

Capacity : 155cc

Vehicle Type : Scooters

Mileage : 31800km

SGD \$13800

Posted on : 07/12/2022

★ Paid Ad

★ Dealer Ad

[Details >](#)

Yamaha Nmax 155

Singapore Tattoo Artist

Walk-in without booking. Get your dreamed tattoo sooner in Singapore

SgShadowTattoo

[Contact Us](#)

Bike Gadgets

[Number Plates for Sale](#)
[Installment Calculator](#)
[Instant Insurance Quote](#)

COE Results

Rd 1, 05 Jan 2023

 COE Bidding of
Motorcycles

CAT D

\$10890

Singapore Tattoo Artist

Walk-in without booking
Get your dreamed tattoo
sooner in Singapore

SgShadowTattoo

[Contact Us](#)



ASSESSMENT FOR REPAIR :FBU150R

YAMAHA NMAX 155 ABS CVT

COE EXPIRY : 21 Jul 2032

Lump Sum / Part by Part

Qty	Description
1	FRONT RIM <i>ny</i>
1	FRONT FORK <i>su</i>
1	HEADLIGHT
1	HEADLIGHT STAY
1	FRONT LH COWLING

Repairer's Estimate	1st Survey	Repair Survey	Final Survey
486.00	☒		
702.00	☒		
486.00	☒		
178.00	☒		
98.00	☒		

1,950.00

Special Nett Items

STEERING CONE & BEARING
FRONT FORK ALIGNMENT
WHEEL ALIGNMENT
FRAME ALIGNMENT

<i>11</i> 120.00	☒		
220.00	☒		
<i>11</i> 120.00	☒		
<i>11</i> 200.00	☒		

660.00

Total Parts

2,610.00

Labour Charges

1 Workmanship to renew damage parts & areas

350.00

350.00

Total Parts & Labours Concluded

2,960.00 Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

*not Authorized
Liu Marcus
90296608
11/1/23
wh photo after repair
2 days*

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com