



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS/AWA23000365/Rvy3m4 Date: 31/03/2023  Code: AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YQ 7460Z	Veh. Inspected	SMW 7108C	
Policy No.	BVF2SB0002782201	Coverage (\$)	0.00	
Claim No.	NSV2200183/PC	Excess (\$)	0.00	
Assign From	GOH STELLA	Assign Date	11/01/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	CITROEN GRAND C4 S.T 1.2	c.c	1199	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	VF73AHNSRKJ816635	Colour	RED	
Odometer	24897 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60R16	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/11/2022	Inspection Date	13/01/2023	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	