



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI23000375/Kny3m4 Date: 22/03/2023  Code: GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKU 5748C	Veh. Inspected	GBL 2541E
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000001284	Excess (\$)	0.00
Assign From	JANELLE TAN	Assign Date	11/01/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN NV200 (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JN1YAAM20Z0001486	Colour	GREY
Odometer	31959 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	165/80 R14	TOYO	7 mm
L/H Front Tyre	165/80 R14	TOYO	7 mm
R/H Rear Tyre	165/80 R14	TOYO	7 mm
L/H Rear Tyre	165/80 R14	TOYO	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	03/01/2023	Inspection Date	13/01/2023
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	