	22 222 2 - 17 2 1
ASS. RECEY: TOUTHER - REF. C/3 (T)	25000 272 1 Vp >
	SIGNMENT
From: Date:	Veh Nor SWK2420Xt Regn: 2019, April.
Estimated lost:	Type: M.Car / M.Cycle / Bus / Van / Lorry /. Taxi / Prime Mover /
OD TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect/Vehicle No:	Make: Mondy Fit-maren c.c 1317
at Workshop m/s	Colour Yellow A/C: Insured / Std / NI / NA
σf	Sp.Reading CK 0/9/15 Use Old Park TiRadio: Insured   Std   NI   NA
insured:	Eng/No:
Policy No.	C/No: 623 346794
Claims Ni	Gen. Cond: Good / Fair / Poor / Burnt
Sum insued: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / SIRitm / STD AJRim or
	Tyre Size: F:
(Policy Condition)	R:
Remark: The veh had commenced its N/S C repair at the time of inspection.	BS I DUN I EXNOVA   GY I-FS I LIZA   MIC   DHTSU   PIR   SUMI
Bal. or Market Value:	TOYO I YOKO DI
IDAC Accident Roort: Consistent? : Yes or No	R/Bal, mm R/Bal. 9 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. L/Bal. mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 11 123 CRSqm
Lum Sum: % 3 Val.: Yes or No	Survey held at HSS4 NE IA-40"
CA / REV / REP. / 24 HRS WP CY	Des. of Damages : Fri / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN Date: Person Contacted;	
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
) Kupar hay i B	13000, -\$15000 14days
1	1
Date/Time, File Page 10? : Preli. Report	Days Of Repair:
i) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Ad	d Fee: : Site Insp (\$ )_s+Rs_sl.
	: Interview (\$ ) Photas
Reprofessional:	: Tech. Irivs (\$ ) Others
· Legitings School of the control of	: Weekend (\$

-

84,275.03	\$	Total Repair Cost	
13,200.00	\$	Total Labour Cost	
£0.870,17	\$	Total Parts Cost	
13,200.00	\$	LATOT AUOBAJ	
atsh			
00.008	\$	SI . Amy	REMOVE AND INSTALL FUEL TANK
00.031 08	\$	,	TO CHECK FOUR WHEEL ALIGHMENT
00.008	2\$/	12 april	REMOVE AND INSTALL REAR UNDER CARRIAGE
00.009 005	\$		REMOVE AND INSTALL FRONT UNDER CARRIAGE
00.031 00	1\$	SA5 NC	REMOVE AND INSTALL CONDENSER AND REFILL AIRC
00.081 XM	\$,	AM HƏIH GNA TV	REMOVE AND INSTALL RADIATOR AND REFILL COOLAI
MN 120.00	\$	1.11 1.02. 1.35	REMOVE & REINSTALL CABIN REAR GLASS

I Total Repair Cost \$ 84,275.03

ILS
BELUMP SUM
SURVEY

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

- To resurvey before/after spray painting
   To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- · Third party survey is on a "Without Prejudice" basis
- Mo illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from insurance Company

Acknowledged by Repairer Signature:

:9160

SJ0C231A0001 / JOO HAK KEE AUTO PTE LTD ENTRY DATE & TIME: 10/01/2023 12:46 (SGT) SUBMITTED BY: Poh Shi Min VERSION: 1 (10/01/2023 12:46 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Actual Driver

  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of Submission

Reported by

Date of Accident **Exact Location of Accident** 

Additional Location Information

Country/State of Loss

10/01/2023 12:46 (SGT)

Both

10/01/2023 08:44 (SGT)

Singapore

SENG KANG TO KPE

Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SMK2420X

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

**Email Address** 

Mobile Phone No

Alternative Phone No.

No

WONG WEN BIN

SXXXX306G

OLEOLE87@OUTLOOK.COM.SG

(Phone) +65-96581433

VEHICLE PARTICULARS

Manufacturer

iviodel

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission CC

Honda

Fit

1.3GF CVT

Private use

No - Claiming third party

Private car

Auto

1317

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

Income Insurance Limited

5125361583

DRIVER

Name of Driver

NRIC No

Date Of Birth

Occupation

Accident report SJ0C231A0001

WONG WEN BIN SXXXX306G 07/02/1987 Indoor

Date Of Driving Pass 16/02/2006 Driving experience 16 YEARS AND 11 MONTHS Gender Male Mobile Number (Phone) +65-96581433 Alt. Phone Number **Email Address** OLEOLE87@OUTLOOK.COM.SG 621A TAMPINES STREET 61 #16-510 Address Address complement Postcode 521621 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

No
Was any other vehicle or property damaged?

Yes
Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
Translator's name

Translator's ID

No

Translator's name
Translator's ID
Translator's phone number
Translator's email
Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Yes

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Contact Number

SLH9927H

SLH9927H

SLH9927H

SLH9927H

SLH9927H

SLH9927H

SLH9927H

SLH9927H

Contact Number

Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

# **DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SMP9006L Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

# INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person WONG WEN BIN Gender Male Phone No (Phone) +65-96581433 Address 621A TAMPINES STREET 61 #16-510 Address Complement Post Code 521621 Approximate Age Years Old Injuries Sustained 2 DAYS MC Injured person in which vehicle? SMK2420X Were seat belts worn? Yes Was this injured conveyed to hospital by ambulance?

On 10th Jan 2023 at 08:44 hrs I was driving towards KPE from
· ·
Singkang.
Due to traffic congestion, I came to a complete stop when the traffic on the first lane freezes.
The most thing I keep CIH 9927 H recognited use
The next thing I knew, SLH 9927 H regrended me from behind causing me to knock the car in front of me.

Declaration
I/We declare the foregoing particulars are true in every respect.

vJun2022

. . 3

#### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow nsurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

# 5. Any false reporting may be referred to the Traffic Police Department for investigation.

- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;


- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

#### Sketch Plan



Uun2023

