SC11231A0003 / CHENG HOE MOTOR PTE LTD[768761] ENTRY DATE & TIME: 10/01/2023 17:47 (SGT) SUBMITTED BY: CHIONG BENG CHOON VERSION: 1 (10/01/2023 17:47 (SGT))

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# **ACCIDENT STATEMENT**

Date of Submission 10/01/2023 17:47 (SGT) Reported by Date of Accident 07/01/2023 11:49 (SGT) Exact Location of Accident Singapore Additional Location Information CTE TOWARDS CITY Country/State of Loss Singapore

# **DETAILS OF OWN VEHICLE**

Vehicle Registration Number GBD4659D

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner LIENTA ENGINEERING & SANITARY WORKS Company Reg No 44992900X Email Address pollytcf@yahoo.com Mobile Phone No (Phone) +65-67594863 Alternative Phone No

## VEHICLE PARTICULARS

Manufacturer Nissan Model NV350 PANEL VAN 2.5 5MT 5DR EURO V Exact purpose for which vehicle was being used at time of accident Employment Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Commercial vehicle

Transmission Manual 2488

# INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Policy Number / Cover Note Number DMCVSNW00127792205

## DRIVER

Name of Driver NG KAH TECK Passport No/FIN G2042448L Date Of Birth 24/12/1993 Occupation Outdoor

Date Of Driving Pass 03/08/2021 Driving experience 1 YEAR AND 5 MONTHS Gender Mobile Number (Phone) +65-86569554 Alt. Phone Number Email Address pollytcf@yahoo.com Address Address complement Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Employee Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER SKETCH ATTACHED ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number **GBK9950S** Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle

TANG HONG HWEE

S1697513C

NRIC No

Name of Driver

Contact Number	(Phone) +65-91816973
Address Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

INSURER CHINA TAIPING
DATE OF ACC 07/01/23 11-49 a.m.

## IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

## (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes/

聯達潔氣水喉公司

LIENTA ENSINEERING & SANITARY WORKS BUX 30 WOODLANDS LINK #06-15 SINGAPORE 758733 TEL: 67594835 FAX: 67598413


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

NL 10/1/2

Witnessed by Reporting Centre Berson (Name as in NRIC/ID card) (Ys)

Sketch Plan



1

2,0253	der your Own Comprehensive policy. Pls chec n Own Policy ( ✓ ) Claim Third party			
		. (	) Reporting Onlly	
) Clair etch Plan	m OD/ TP at other workshop (			
auti rian	71-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-			
	GBD 4659D	GBK 99505		
	INNE!	5		
	IAME 2 DE COM	4		
	LANE 3	4		
	LANE 4	4		
	LANES	4		1111
		THAT!	HHERRI	1111
	CTE ZOWNEDS CITY			
1 1 1		TITITI		
was	moving at lane 2 and trafficient brake and I also be a vehicle (GBIC 99505) come	valce my	vehicle on time.	3ut
ebiide uddenly	infront brake and I also b a vehicle (GBIC 99505) come	forward	vehicle on time.	3ut
L was ehide uddenly	infront brake and I also b	forward	vehicle on time.	3ut
L was ehide uddenly	infront brake and I also b a vehicle (GBIC 99505) come	forward	vehicle on time.	3ut
L was ehide uddenly	infront brake and I also b a vehicle (GBIC 99505) come	forward	vehicle on time.	3ut
L was ehide uddenly	infront brake and I also b a vehicle (GBIC 99505) come	forward	vehicle on time.	3ut
L was ehide uddenly	infront brake and I also b a vehicle (GBIC 99505) come	forward	vehicle on time.	3ut
L was was	infront brake and I also b a vehicle (GBIC 99505) come	forward	vehicle on time.	3ut
L was was	infront brake and I also b a vehicle (GBIC 99505) come	forward	vehicle on time.	3ut
L was was	infront brake and I also b a vehicle (GBIC 99505) come	forward	vehicle on time.	3ut
was was addenly hick re	infront brake and I also b a vehicle (GBIC 99505) come car portion and cause damange	forward	vehicle on time.	3ut
was was addenly hick re	infront brake and I also b a vehicle (GBIC 99505) come	forward	vehicle on time.	3ut















