
(08/11/13) We REF:	- 3 3
ASS. REC. BY: VILLE ASS	IGNMENT
From: Date:	Veh No: SOB 59572 Yr Regn: 708 / DEC
Estimated Cost:	Type: N.C.2 / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD'TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No: SDB SAS72	Make: Audi 483.0 TESI QUITIP C.C 2898
at Workshop m/s Premuv	Colour Buyer A/C: Insured / Std / NI / NA
of Dy, Brown section	Sp.Reading 30486 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WALL ZZZ F8 2 KN 00 8271
Claims No.	Gen. Cond: Good / Pal / Poor / Burnt
Sum Insured: Excess: TBA	Steering: Inorde / Jammed / Leaked / Burnt or
(Client's Record)	Brake: norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / SRim / STD A/Rim or
	Tyre Size: F: 365 (40220
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: 246K	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. L/Balmm
Est. Repairs: days Res.: Yes or No	D.O.A. 07 01 23
Lum Sum: % 3 Val.: Yes or No	Survey held at PRENIUM
CA / REY / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction REPAUL LAT - 1414	
	A STATE OF THE PROPERTY OF THE
Date/Time, File Pass to? : Prell. Report	Days Of Repair:
1) : Final Report .	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add F	ee:: Site Insp (\$)s+Rssi
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$:Weekend (\$
Lump Gum / Nom (4	politica contract participation and the contract participation

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE

: ACCIDENT REPAIRS

WORKSHOP

: UBI ROAD 1 : 6366 2323

CONTACT NO FAX NO

: 6841 1183

REFERENCE

PA/OD/0022/2023/EQ

DATE

: 10-Jan-23

WIP

58198

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/1/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME

MS COUDRAY BOOKER MARIE EMMANUELLE LUCIE

ADDRESS

: 14 SWISS CLUB ROAD

SINGAPORE 288107

TELEPHONE

: HP +65 96253450

TYPE OF CLAIM

OWN DAMAGE CLAIM

POLICY NO

1800152122-03

VEHICLE NO

SDB 5957 Z

MODEL CODE

: AUDI A8 D5 3.0 TFSI

MODEL YEAR

31/12/2018

ENGINE NO

CZS 016956

CHASSIS NO

WAUZZZF82KN006271

MILEAGE

30,486

DATE IN

30,400

DAILIN

9-Jan-23

ESTIMATED BY

JOHNNY BOO / ALLAN WU


ACCIDENT DATE

7-Jan-23

PLACE OF ACCIDENT

JALAN ANAK BUKIT





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDB 5957 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	\$	480.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	\$	450.00	300
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	•		100
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$		60 1200
5	TO CARRY OUT CALIBRATION FOR FRONT BUMPER 360 S/N CAMERA, DISTANCE REGULATION AND RADAR SENSOR.		480.00	
6	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST S/N WHEEL ALIGNMENT.	\$	520.00	320
7	TO CARRY OUT DIAGNOSTIC CHECK. S/N	\$	192.00	
	TOTAL LABOUR CHARGES :	\$	6,822.00	= = , ~





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 5957 Z

DAMAGED PARTS & PRICES

			DAMAGED FART	J & 1 112025
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER de	1	\$ 3,985.00	
2	FRONT BUMPER FIXING PARTS .	1	\$ 570.00	
3	FRONT BUMPER CLOSING ELEMENT	1	\$ 456.00	
4	FRONT BUMPER COVER - CENTER 7	1	\$ 77.00	
5	FRONT BUMPER COVER - LH / RH	2	\$ 176.00	
6	FRONT BUMPER BRACKET (H) RH	12	\$ 260.00	
7	FRONT BUMPER GRILLE - LOWER CENTRE	1	\$ 551.00	
8	FRONT BUMPER CHROME TRIM - 🍎 🗸 RH 🗡	12	\$ 450.00	
9	FRONT BUMPER TRIM CAP - LH	1	\$ 18.00	
10	FRONT BUMPER END CAP - CAP / RH	12	\$ 138.00	
11	FRONT BUMPER AIR GUIDE GRILLE - 67/RH 🗶	12	\$ 1,404.00	
12	FRONT BUMPER OUTER TRIM - LH REAR UPPER	1	\$ 260.00	
13	FRONT BUMPER OUTER TRIM - 6 / RH LOWER ?	1/	\$ 520.00	
14	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 310.00	
15	FRONT BUMPER SPOILER .	1	\$ 349.00	
16	FRONT BUMPER LOWER COVER BRACKET	1	\$ 94.00	
17	RADIATOR GRILLE ZVA	1	\$ 2,631.00	
18	"QUATTRO" INSCRIPTION	1	\$ 118.00	
19	RADIATOR GRILLE COVER .	1	\$ 74.00	
20	RADIATOR GRILLE COVER CAP	1	\$ 149.00	
	SUB TOTAL SPARE PARTS	:	\$ 12,590.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 5957 Z

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
	7	9	ć	56.00	
21	RADIATOR GRILLE BRACKET	1	\$		
22	RADIATOR GRILLE END CAP - LH / RH .	2	\$	54.00	
23	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE .	1	\$	209.00	
24	FRONT BUMPER AIR GUIDE (L) / RH 🗡	12	\$	158.00	
25	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$	120.00	
26	FRONT LICENCE PLATE HOLDER	1	\$	972.00	
27	FRONT BUMPER SUPPORT (H / RH	12	\$	72.00	
28	FRONT BUMPER FOAM FILLER PIECE 7	1	\$	149.00	
29	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$	1,412.00	
30	FRONT BUMPER CROSS MEMBER .	1	\$	430.00	
31	FRONT BUMPER GUIDE SECTION - LH	1	\$	71.00	
32	FRONT REBOUND STRAP	1	\$	94.00	
33	FRONT BUMPER BRACKET 7	1	\$	36.00	
34	FRONT BUMPER TOP COVER CM	1	\$	236.00	
35	FRONT BUMPER TOP COVER CAP 7	1	\$	41.00	
36	AIR CONDITIONER STICKER 🛰 🖊	1	\$	24.00	
37	CAUTION SIGN STICKER 🛰 /	1	\$	17.00	
38	HORN HIGH TONE - RH	1	\$	165.00	
39	HORN BRACKET - UPPER	1	\$	27.00	
40	HORN BRACKET - LOWER ?	1	\$	56.00	
	SUB TOTAL SPARE PARTS	:	\$	4,399.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 5957 Z

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
	-			
41	FRONT PARKING AID SENSOR - INNER	2	\$ 598.00	
42	FRONT PARKING AID SENSOR - OUTER CA	1 %	\$ 598.00	
43	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 598.00	
44	FRONT PARKING AID SEAL RING	4	\$ 11.00	
45	FRONT BUMPER WIRING SET	1	\$ 756.00	
46	FRONT FENDER - LH tom	1	\$ 3,088.00	
47	FRONT FENDER BRACKET - LH FRONT	1	\$ 100.00	
48	FRONT FENDER BRACKET - LH CENTRE	1	\$ 74.00	
49	FRONT FENDER BRACKET - LH UPPER -	1	\$ 35.00	
50	FRONT FENDER BRACKET - LH UPPER 7	1	\$ 54.00	
51	FRONT FENDER BRACKET - LH LOWER 7	1	\$ 42.00	
52	FRONT FENDER BRACKET - LH REAR 7	1	\$ 74.00	
53	FRONT FENDER BRACE - LH INNER ?	1	\$ 642.00	
54	FRONT FENDER BRACE - LH OUTER 7.	1	\$ 180.00	
55	FRONT FENDER CONNECTING PIECE - LH	1	\$ 215.00	
56	FRONT FENDER RETAINING BRACKET - LH	1	\$ 22.00	
57	FRONT FENDER ATTACHMENT PARTS ?	1	\$ 65.00	
58	FRONT WHEEL HOUSING LINER - LH	1	\$ 495.00	
59	FRONT WHEEL SPOILER - LH	1	\$ 112.00	
60	FRONT WHEEL SPOILER STONE CHIP GUARD - LH $?$	1	\$ 60.00	
	SUB TOTAL SPARE PARTS	:	\$ 7,819.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDB 5957 Z

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT FENDER CHROME LINING - LH	1	\$ 190.00	
62	HEADLIGHT-LH CA	1	\$ 14,751.00	
63	LIFT CYLINDER - LH / RH	2	\$ 630.00	
64	LIFT CYLINDER HOSE 7	1	\$ 104.00	
65	LIFT CYLINDER PIPE 7.	1.	\$ 72.00	
66	TO THE TEN AND THE MATTER RESERVOIR	1	\$ 476.00	
67	SIA SIA	1	\$ 3,338.00	
68	THE TAXABLE DIM DIDDED VALVE	1	\$ 4.00	
6	hu /	S/N	\$ 60.00	
	O SUNDRIES ?		\$ 500.00	
	0 351151.11=1		 44.022.00	
	TOTAL SPARE PARTS	•	\$ 44,933.00	
	TOTAL LABOUR CHARGES	•	\$ 6,822.00	
	GRAND TOTAL	:	\$ 51,755.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

♣ PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

RASUL - He 90010068

11/01/23 & 1440
6 days

Excess: That

Revere

Resur before point

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE

AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO **BODY REPAIR MANAGER** **ALLAN WU CLAIMS CONSULTANT** MARY DATE & TIME: 09/01/2023 17:49 (SGT) ATRY DATE BY: FOONG CHIN FONG SIBMITTED BY: FOONG CHIN FOONG SIBMITTED BY: FOONG CHIN F



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1, Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

2. This remains a structure of the companies to repudiate a structure of the companies and the companies are repudiate as the companies and the companies are repudiate as the companies are reputational as th

A. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

4. The Issue reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 09/01/2023 17:49 (SGT) Reported by Date of Accident 07/01/2023 13:53 (SGT) Exact Location of Accident Jln Anak Bukit, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SDB5957Z

INSURED/POLICYHOLDER

Is company? COUDRAY BOOKER MARIE EMMANUELLE LUCIE Name Of Registered Owner NRIC No SXXXX275D EMMANUELLEBOOKER@GMAIL.COM Email Address (Phone) +65-96253450 Mobile Phone No Alternative Phone No

VEHICLE PARTICULARS

Audi Manufacturer Model **D5 3.0 TFSI** Variant Exact purpose for which vehicle was being used at time of Private use Are you claiming under your own insurance policy for repair to Yes your vehicle? Private car

Vehicle Category Auto Transmission 2995

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number AIG Asia Pacific Insurance Pte. Ltd. 1800152122-03

DRIVER

Name of Driver NRIC No Date Of Birth Occupation COUDRAY BOOKER MARIE EMMANUELLE LUCIE SXXXX275D 26/09/1975 Indoor

Of Driving Pass	
of Driving Pass	12/07/2018
ning experience	4 YEARS AND AME
Gender Sumber	4 YEARS AND 6 MONTHS Female
Work and Number	
Att maddress	(Phone) +65-96253450
Email Address	FMMANUELLEDOOUSE -
Address	EMMANUELLEBOOKER@GMAIL.COM 14 SWISS CLUB ROAD
Address complement	- CANOS CLOB ROAD
Postcode	288107
is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	110
Laurance Company of Other Vehicle Owned L. D.	•
Insurance Company of Other Vehicle Owned by Driver	*
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	011-0-1
Weather Conditions	Side Swipe
Road Surface	Clear
the state of the s	Dry
1775 L. S. Mar. T. Waller, Co. Co. Co. Co. Co. Co.	
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s)	Na
soliciting/offering accident claims assistance?	No
Translator's name Translator's ID	-
Translator's ID Translator's phone number	-
Translator's email	-
Original language used in the statement	-
Original language used in the estate	
PASSENGER 1	
Name	MARIA ZENIERIS
Gender	Female
Gender	
PASSENGER 2	
Name	YUONNE ZENIERIS
Gender	Female
PASSENGER 3	
Name	PETROS ZENIERIS
Gender	Male
DETAILS OF POLICE ACTION	
SETTILE ST. 7 SEISETTSTIME	
Weether assistant removed to the police?	M -
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	•
CIRCUMSTANCES OF ACCIDENT	
LEFT TURN TO CHANGE LANES, HIT BY A BUS. BUS CONTI	NUED UPON IMPACT FOR THE LENGTH OF THE BUS.
ATTACHMENT(S)	
The same of the same of	
Ave assident photos quallable for attachment?	Yes
Are accident photos available for attachment?	100

Accident report SP1423190006

DETAILS OF OTHER VEHICLE PROPERTY 1

Secretion Number	
Vehicle Registration Number Vehicle Manufacturer	SMB1436E
LIMO MICHAEL	-
vehicle Model vehicle Model	•
Vehicle Variant	•
Vehicle Colour	
vehicle Category	Bus
Name of Driver Contact Number	
	-
Address complement	-
	-
Postcode Insurance Company Name	=
Nature Of Damage	=
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-
NO. Ot 1 docongs. (=:

SKETCH PLAN

IMPORTANT NOTICE

- 1. Rease report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknow ledge, agree and consent that;

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Porsonal Information") and disclose and transfer such Personal Information to a linsurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the poice), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

2 Time

- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administoring, processing, handling and/or dealing with my claims

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect,

Driver's Signature (# driver is not the policyholder) / Date

use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

14:39

09/01/2023

Witnessed by Reporting Centre Personnel long Foory

Policyholder's Signature / Date &

Sketch Plan

A-5085957Z

7 - SMB 1436E

-	- bad	turr	١.	1.			_										
١	rit	turr	<u></u>	10	Cho	nac	(che	1								
	1	(3)	100	77													
	OV-	Thus	cl	upo	N I	mpa	cf	Cor	la.	1)							
		ihus						1	len	344	0	b	.5				
							_										
							_							_			
													/		 		
							-					_/			 		
			decreases and									_			 		
										/					 		
									-	_							
				No. of Contract of													
							/						10.5		 		
						1	/										
						/		4.5							 		
						/											
			_		1										 		
					7												
				-/											 		
				1											 		
			_	/											 		
			-1												 		
			+												 	-	
			1											_	 		
		-										,			 		
		-/								_							
		-/-															
		-													 		
		/															
	-																
-												-		-			
Dec	larat	ion															
		e the for	eggin	g partic	ulars	are true	in ev	ery res	pect.								
Me	decla	e the ion	-3-												/	(15) A/O	
													1630)	(3)	A	
									01		09/	01/20	23		1.	(+)	919
								1/1	2/m				r) / Date		1	रा अह	ting Center
		er's Sign				_	2000						41 / 17440				

- Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

owner ID Type:	Singapore NRIC
Owner ID.	275D
Vehicle No.	SDB5957Z
Vehicle to be Exported:	No.
Intended Deregistration Date:	12 Jan 2023
Vehicle Make:	AUDI
Vehicle Model:	AB3.0TFSIQUTIP(SR, 20")
Primary Colours	Blue
Manufacturing Year	2018
Engine No.	CZS016956
Chassis No.	WAUZZZF82KN006271
Maximum Power Output:	2500 kW (335 bbp)
Open Market Value:	\$74,919.00 PER SECOND S
Original Registration Date:	31 Dec 2018
First Registration Date	31 Dec 2018
Transfer Count	
Actual ARF Paid	\$104,855.00
PARF Eligibility	
PARF Eligibility Expiry Date:	30 Dec 202B
PARF Rebate Amount:	\$80 141.00
COE Expiry Date:	30 Dec 2028
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10 10
OP Paid:	531,001.00
COE Rebate Amount	318,492.00
Total Rebate Amount:	\$98,633.00
e information contained herein is correct as at 12 Jan 2023	

Audi A8L Mild Hybrid 3.0A TFSI Quattro Tip

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price

\$233,888

Depreciation 🛞

\$31,620 /yr

View models with similar depre

Reg Date

11-Sep-2018

(5vrs 7mths 29days COE left)

Mileage

22,000 km (5.1k /yr)

Manufactured (1)

2018

Road Tax

\$2,38**0 /yr**

Transmission

Auto

Dereg Value (1)

\$100,201 as of today (change)

Fuel Type

Petrol-Electric

COE (1)

\$32,001

OMV (2)

\$76,348

Engine Cap

2,995 cc

ARF

\$109,427

Curb Weight



2,020 kg

Power

250.0 kW (335 bhp)