

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS/SMO23000413/Kqy3q2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623		Date:	03/02/2023	
				Code:	SMO	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJF 9929L	Veh. Inspected	t	SMD 6366E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2300171/RUC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		12/01/2023	
2. Vehicle Particulars & Condition						
	Make & Model	B.M.W. 740LD (A)	c.c		2993	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	WBA7G82040GS39075	Colour		METALLIC GREY	
	Odometer	113697 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/40 R20	GOODYEAR		8 mm	
	L/H Front Tyre	245/40 R20	GOODYEAR		8 mm	
	R/H Rear Tyre	275/35 R20	GOODYEAR		8 mm	
	L/H Rear Tyre	275/35 R20	GOODYEAR		8 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	31/12/2022	Inspection Dat	te	16/01/2023	
	Survey held at	RC AUTO				
		160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					