

ASS. REC BY: Toujan


REF: CS/TM1-23000417/Tuys

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: S4C 562J Yr Regn: 20/81 Ang
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Wing C.C. 1580
 Colour: Yellow A/C: Insured / Std / NI / NA
 Sp. Reading: 732531 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMH851 CLK 0107311
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 195/65R15
 R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /
 TOYO / YQKO or Westlake

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS WP
 Date: _____ Person Contacted: UMTS Vehicle: IN / OUT

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 12/1/23
 Survey held at Compass by ay
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format: _____
 Lump Sum / L.S.F.: _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. \$ _____
 Photos _____
 Others _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**

CCPL
Singapore

(LKS)
LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	10/01/2023
Vehicle Reg. No.:	SHC562J	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	21/08/2018
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEJU080637	Chassis No:	KMHC851CVKU107311
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,722.20
Miscellaneous Items	11.00
Labour	3,100.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,833.20
+ GST 8.00% (S\$)	466.66
Nett Amount (S\$)	6,299.86

This claim is handled by: LIM TIEN SIONG

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Jan 2023)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: **ComfortDelGro Engineering Pte Ltd/SHC562J/11/01/2023 14:24**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR LH	20.00	0.00	1,797.20 FL
2	1		*FRONT FENDER (BLUEDRIVE) LH	20.00	0.00	26.60 FL
3	1		*FRONT DOOR PROTECTOR LH	20.00	0.00	186.20 FL
4	1		*REAR DOOR PROTECTOR LH	20.00	0.00	166.20 FL
5	1		*ROCKER PANEL GARNISH LH	20.00	0.00	290.00 FL
6	1		*FRONT WHEEL CAP LH	20.00	0.00	346.40 FL
7	1		*REAR WHEEL CAP LH	20.00	0.00	346.40 FL
8	1		*FRONT DOOR COMFORTDELGRO LH	0.00	0.00	75.00 F
9	1		*REAR DOOR ZIG LH (APPS STICKERS)	0.00	0.00	80.00 F
10	1		*REAR FENDER (PETROL ONLY) LH	0.00	0.00	40.00 F
				Sub Total (\$\$)		3,354.00
				- List Item Discount on L Items (\$\$)		631.80
				Total Parts (\$\$)		2,722.20

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHC562J/11/01/2023 14:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING - FRT FENDER LH & REAR FENDER ARCH LH ETC	New 700	1,200.00
2	SPRAY PAINTING	New 1400	1,500.00
3	TUFF KOTE	New 30	100.00
4	CHECK WIRINGS	New X	60.00
5	TRANSFER OF DOOR	New 60	120.00
6	WHEEL ALIGNMENT	New 80	120.00
Gross Labour Cost (\$\$)			3,100.00

ComfortDelGro Engineering Pte Ltd/SHC562J/11/01/2023 14:24. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanglin 97445749
 WP 12/1/23 @ 4pm
 L/S Resurvey after repair
 fender & LH arch. is in
 03 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature: _____
 Date: _____

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5613330

JC NO.305542346

OWNER

CITYCAB PTE LTD
 7010070
 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 65551188

REGN NO: SHC 562J	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 10.01.2023 19:05
YR OF MANU 21.08.2018	TARGET DATE
CHASSIS CODE KMHC851CVKU107311	COMPLETION DATE/TIME:


IDENT CARD NO.

JOB DESCRIPTION

Accident Date: 10.01.2023
 NATURE: 3P 10.01.2023

NO	LABOR CODE
00010	PB
00020	20-05

DESCRIPTION
 PANEL BEATING-SHC 562J-TP
 TP MERIMENT



RECEIVED & PASSED OUT BY: _____

 SERVICE ADVISOR

 CUSTOMER'S SIGNATURE

Assessment Slip

Exit Pass

Vehicle No.: **SHC 562J** **LIMITS**

Vehicle No.: **SHC 562J**

 Service Advisor

 Signature/Date

 Name of Service Advisor

 Date

Returned to Service Reception upon collection

To be kept by Security Guard