



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 873A

### Vehicle Details

Vehicle No.: SKK1788R  
Vehicle to be Exported: No  
Intended Deregistration Date: 30 Dec 2022  
Vehicle Make: TOYOTA  
Vehicle Model: VIOS J AUTO  
Primary Colour: Black  
Manufacturing Year: 2008  
Engine No.: 1NZX808177  
Chassis No.: MR053HY9305081831  
Maximum Power Output: 80.0 kW (107 bhp)  
Open Market Value: \$11,434.00  
Original Registration Date: 10 Dec 2008  
First Registration Date: 10 Dec 2008  
Transfer Count: 3  
Actual ARF Paid: \$11,434.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 09 Dec 2023  
COE Category: E - Open Category  
COE Period(Years): 5  
PQP Paid: \$13,786.00  
COE Rebate Amount: \$2,594.00  
**Total Rebate Amount: \$2,594.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Dec 2022

OK

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	30/12/2022 18:18 (SGT)
Reported by	Driver
Date of Accident	30/12/2022 10:40 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	EUNOS ROAD 2
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SKK1788R

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ANG NGOH ENG
NRIC No	SXXXX873A
Email Address	angteckgee@gmail.com
Mobile Phone No	(Phone) +65-98585999
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	VIOS J AUTO
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1497

### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5123902353-01

### DRIVER

Name of Driver	ZHONG YONGHUI
NRIC No	SXXXX484H
Date Of Birth	25/06/1992
Occupation	Indoor

Date Of Driving Pass	30/12/2022
Driving experience	0 MONTH
Gender	Male
Mobile Number	(Phone) +65-96348932
Alt. Phone Number	-
Email Address	zhongyonghui92@gmail.com
Address	BLK 75C REDHILL ROAD #25-78
Address complement	-
Postcode	153075
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	LEARNER
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	ANG TECK GEE (INSTRUCTOR)
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I was having driving tuition with my instructor (Mr Ang Teck Gee) seated beside me. I was going straight (Eunos Road 2), SMB3592Z dashed out from bus interchange without stopping & collided onto left portion of my car.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMB3592Z
Vehicle Manufacturer	-
Vehicle Model	-


Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	ZHAN FUJUN
Passport No/FIN	GXXXX180T
Contact Number	(Phone) +65-81210733
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Describe Circumstance of the Accident

\*\* NOTE: PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

- ( ) Claim Own Policy      ( / ) Claim Third party      ( ) Reporting Only  
 ( ) Claim OD/ TP at other workshop ( \_\_\_\_\_ )

Sketch Plan



A: SKK 1788R

B: SMB 3592Z

Zhan Fu Jun

G 272 1180T

HP: 8121 0733

DOA: 30/12/22 10.40am

I was having driving tuition with my instructor (Mr Ang Teck Gee) seated beside me. I was going straight (Eunos Road 2), SMB 3592Z dashed out from bus interchange without stopping & collided onto left portion of my car.

Declaration

I/We declare the foregoing particulars are true in every respect.

*Zhang Yonghu*

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

(YS) Ong 30/12/22  
 Witnessed by Reporting Centre Personnel  
 (Name as in NRIC/ID card)

VEH NO: SKK1788R  
INSURER: Income  
DATE OF ACC: 30/12/22 10:40 am

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

\_\_\_\_\_  
Policyholder's Signature / Date & Time

zhong kongshu  
\_\_\_\_\_  
Driver's Signature (if driver is not the policyholder) / Date & Time

(YS) ong 30/12/22  
\_\_\_\_\_  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

**Sketch Plan**

PLEASE  
TURN  
OVER

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SKK1788R  
 TP/SMRT

M/S : SMRT AUTOMOTIVE SERVICES PTE LTD  
 60 WOODLANDS INDUSTRIAL PARK E4  
 SINGAPORE 757705

Estimate No: ES2300040/YISHUN  
 Date: 12 Jan 2023  
 Policy No: 5123902353-01  
 Veh Reg No: SKK1788R  
 Make/Model: TOYOTA TOYOTA VIOS  
 J AUTO  
 Chassis No: MR053HY9305081831  
 Engine No: 1NZX808177  
 Reg. Date: 10/12/2008

TEL: 64823888 FAX: 63687421  
 ATTN: Motor Claim Department

WS Ref: TP/SMRT  
 Claim Type: Third Party  
 Accident Date: 30/12/2022  
 TP Veh Reg No: SMB3592Z

*Not within  
 1/1yr @ 5850/h  
 Premium After Repair  
 9 days*

## Estimate Repair Cost to Vehicle No :SKK1788R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
<b>List Price</b>				
1 FRONT LH DOOR <i>1188.10</i>	1,188.20	1 PC	<i>By</i> 1,188.20	<i>✓</i>
2 FRONT LH DOOR BLACK TAPE	63.20	1 PC	<i>Na</i> 63.20	<i>✓</i>
3 FRONT LH DOOR OUTER HANDLE <i>Nil/Nil</i>	196.10	1 PC	<i>Nil</i> 196.10	<i>✓</i>
4 FRONT LH DOOR OUTER HANDLE KNOB	48.80	1 PC	<i>Nil</i> 48.80	<i>✓</i>
5 FRONT LH DOOR OUTER HANDLE KNOB GASKET	19.80	1 PC	<i>Na</i> 19.80	<i>✓</i>
6 FRONT LH DOOR GLASS OUTER MOULDING	118.90	1 PC	<i>Nil</i> 118.90	<i>✓</i>
7 FRONT LH DOOR GLASS REGULATOR	248.70	<i>Nil</i> 1 PC	<i>Nil</i> 248.70	<i>✓</i>
8 FRONT LH DOOR INNER LOCK	388.20	1 PC	<i>Nil</i> 388.20	<i>✓</i>
9 LH CENTRE PILLAR	512.30	1 PC	<i>R</i> 512.30	<i>X</i>
10 REAR LH DOOR BLACK TAPE	67.80	1 PC	<i>Na</i> 67.80	<i>✓</i>
11 REAR LH DOOR OUTER HANDLE	192.80	1 PC	<i>Na</i> 192.80	<i>✓</i>
12 REAR LH DOOR GLASS OUTER MOULDING	129.10	1 PC	<i>By</i> 129.10	<i>✓</i>
13 REAR LH DOOR GLASS REGULATOR	221.80	1 PC	<i>By</i> 221.80	<i>✓</i>
14 REAR LH DOOR GLASS REGULATOR MOTOR	324.80	1 PC	<i>By</i> 324.80	<i>✓</i>
15 REAR LH DOOR INNER LOCK	339.80	1 PC	<i>Nil</i> 339.80	<i>✓</i>
16 REAR LH FENDER	999.40	1 PC	<i>By/By</i> 999.40	<i>✓</i>
17 REAR WINDSCREEN GLASS MOULDING	79.40	1 PC	<i>Na</i> 79.40	<i>✓</i>
18 REAR BUMPER	503.20	1 PC	<i>By/By</i> 503.20	<i>✓</i>
19 REAR BUMPER CLIPS	3.50	6 PCS	<i>Na</i> 21.00	<i>✓</i>
20 REAR BUMPER LH RETAINER	89.70	1 PC	<i>By</i> 89.70	<i>X</i>
21 REAR LH DOOR <i>1021.70</i>	1,021.70	1 PC	<i>By</i> 1,021.70	<i>✓</i>
			6,774.70	
		Less 25%	1,693.68	5,081.03
<b>Special Net</b>				
22 REAR LH DOOR SUN VISOR	120.00	1 PC	<i>Na</i> 120.00	<i>60%</i>
23 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	<i>Na</i> 40.00	<i>✓</i>
24 LH SIDE SKIRT	320.00	1 PC	<i>R</i> 320.00	<i>X</i>
			480.00	480.00

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

M/S : SMRT AUTOMOTIVE SERVICES PTE LTD  
 60 WOODLANDS INDUSTRIAL PARK E4  
 SINGAPORE 757705

TEL: 64823888 FAX: 63687421  
 ATTN: Motor Claim Department

WS Ref: TP/SMRT  
 Claim Type: Third Party  
 Accident Date: 30/12/2022  
 TP Veh Reg No: SMB3592Z

Estimate No: ES2300040/YISHUN  
 Date: 12 Jan 2023  
 Policy No: 5123902353-01  
 Veh Reg No: SKK1788R  
 Make/Model: TOYOTA TOYOTA VIOS  
 J AUTO  
 Chassis No: MR053HY9305081831  
 Engine No: 1NZX808177  
 Reg. Date: 10/12/2008

## Estimate Repair Cost to Vehicle No :SKK1788R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
<b>Labour</b>				
25 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
26 REMOVE & INSTALL MID INTERIOR TRIMS,GARNISHES,SEATS AND CARPET, ETC	120.00	1 LA	120.00	100
27 REMOVE LH MID DAMAGED DOORS,REAR BUMPER,CUT OUT LH CENTRE PILLAR,REAR FENDER. PANEL BEAT & REPAIR LH PILLAR INNER PANEL,LH REAR INNER WHEEL HOUSE. REPAIR REAR BUMPER,REALIGN,REPLACE & WELDING BODY PANELS,TRANSFER BOTH LH DOORS PARTS	1,400.00	1 LA	1,400.00	1000
28 SPRAY PAINTING - BOTH LH DOORS,OUTER HANDLE & KNOBS,CENTRE PILLAR,LH REAR FENDER,FUEL TANK DOOR,REAR BUMPER & INNER PANELS,LH SIDE SKIRT	1,400.00	1 LA	1,400.00	1200
29 REPAIR AND RESPRAY LH REAR ALLOY WHEEL RIM	100.00	1 LA	100.00	800
30 RUSTPROOFING	100.00	1 LA	100.00	90
			3,240.00	3,240.00
			Total	SS 8,801.03
			Add GST @ 8%	704.08
			Total Amount Payable	SS 9,505.11

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE