

(08/11/13) Wef
ASS. REC. BY: Z. J. J.

REF:

CS3/ASM 23000.424/Rmp³


7537

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: AW 8484 B
at Workshop m/s HUP HIN
of 1006, PRAKAT MERAH LN 2 #61-02
Insured: ASM
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 17K
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: AW 8484 B Yr Regn: 2020 / OCT
Type: M. Car / M. Cycle Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: YAMAHA C2D 300A Xmax 300cc 292
Colour: BLACK A/C: Insured / Std / NI / NA
Sp. Reading: 28886 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MH 35H 0840L K012460
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 120/70-15
R: 140/70-14
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	<u>4</u> mm	R/Bal.	<u>4</u> mm
L/Bal.	mm	L/Bal.	mm
D.O.A.	<u>04/01/23</u>	D.O.I.	<u>12/01/23</u>
Survey held at <u>HUP HIN</u>			
Des. of Damages: Frt / Rear / <u>O/S</u> / <u>N/S</u> / U/C / Rooftop or			

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 13K

ESTIMATE REPAIR RANGE / No. of days - (2K-3K) / 4 days

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	753F
Vehicle Details	
Vehicle No.:	AWB484B
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jan 2023
Vehicle Make:	YAMAHA
Vehicle Model:	CZD300A / XMAX300
Primary Colour:	Black
Manufacturing Year:	2020
Engine No.:	H336E0092031
Chassis No.:	MH35H0840LK012460
Maximum Power Output:	-
Open Market Value:	\$4,394.00
Original Registration Date:	19 Oct 2020
First Registration Date:	19 Oct 2020
Transfer Count:	1
Actual ARF Paid:	\$660.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Oct 2030
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,310.00
COE Rebate Amount:	\$3,347.00
Total Rebate Amount:	\$3,347.00

The information contained herein is correct as at 12 Jan 2023

Yamaha Xmax 300

Listing Type	Paid Ad
Brand	Yamaha
Model	Yamaha Xmax 300
Engine Capacity	292cc
Classification	Class 2A
Registration Date	08/10/2020
COE Expiry Date	07/10/2030 (7yrs 8mths 25days COE left)
Mileage	-
No. of owners	-
Type of Vehicle	Scooters

SGD **\$17200**