
(08/11/13) ABI	. 1 :
ASS. REC. BY: REF:	5690
ASSIC	SNMENT
From: Date:	Veh No: SWA 4150C Yr Regn: 2021 / Jun
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TTP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SNA 4150C	Make: Aug A3 SOMMUISTES I STRANKE 1498
at Workshop m/s PREMUM	Colour BLUE A/C: Insured / Std / NI / NA
of 24, Maro 1 segre	Sp.Reading 20169 T/Radio: Insured / Std / NI / NA
Insured: ALL	Eng/No:
Policy No.	C/No: WAYU ZZZA Y XMAO8 9991
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: 78A	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 125/45R17
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIE/ SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value: 143k	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est Repairs: days Res.: Yes or No	D.O.A. (0/01/23 D.O.I. 12/01/23
Lum Sum: % 3 Val.: Yes or No.	Survey held at PREMIUM
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S/ N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction  REPAIR LIMIT - 80K	
Kindin Chief OOK	
a a see a	
***	
Date The Date 12	Davis Of Bonnies
Date/Time, File Pass to? : Preli. Report	Days Of Repair:  Resurvey No. of Trip: Survey Fee:
1) : Final Report	
LEADER TOP FIRE REPORT IN C	Transportation:
	Transportation:  Site Insp. (\$ ) S+RS_SI
2) Add Fe	e:: Site Insp (\$)s+Rssi
2) Add Fe	e: : Site Insp (\$ )S+RSSI : Interview (\$ ) Photos
	e: : Site Insp (\$ )S+RSSI : Interview (\$ ) Photos

# \* PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS

 WORKSHOP
 : UBI ROAD 1

 CONTACT NO
 : 6366 2323

 FAX NO
 : 6841 1183

**REFERENCE** : PA/OD/0032/2023/EQ

**DATE** : 11-Jan-23 **WIP** : 58498

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/1/2023

#### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

**TELEPHONE** 

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS JACQUELINE EMMA D/O CHARLES CHRISTIAN

ADDRESS : 198 DEPOT ROAD

#12-37

SINGAPORE 109693 : HP +65 94377266

TYPE OF CLAIM : OWN DAMAGE CLAIM POLICY NO : 7210063619-01

VEHICLE NO : SNA 4150 C

MODEL CODE : AUDI A3 SEDAN 1.5 TFSI

MODEL YEAR : 22/6/2021 ENGINE NO : DFY 263535

CHASSIS NO : WAUZZZGYXMA089991

MILEAGE : 20,169

DATE IN : 10-Jan-23

ESTIMATED BY : JOHNNY BOO / ALLAN WU

ACCIDENT DATE : 10-Jan-23

PLACE OF ACCIDENT : KPE TOWARDS CITY BEFORE EXIT 9A





# ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 4150 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N	\$ 360.00	X
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 480.00	×
3	TO RENEW REAR WINDSCREEN AND RHS REAR 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N	\$ 600.00	
4	TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES.	S/N	\$ 400.00	
5	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N	\$ 290.00	150
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N	\$ 1,400.00	
	TOTAL LABOUR CHARGES	:	\$ 3,440.00	





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

# ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 4150 C

S/N	NATURE OF JOBS			STIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N	\$	1,400.00	/
8	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, AB PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N	\$	1,800.00	X
9	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	\$	700.00	/.
10	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N	\$	800.00	X
11	TO SETUP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N	\$	2,400.00	×
12	TO DISMANTLE AND REINSTALL REAR BUMPER AND FRONT BUMPER. TO RENEW RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. TO CUT OUT AND WELD RHS APILLAR, RHS B-PILLAR, RHS SILL PANEL AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	353	70×7	11,900.00	Youv
	TOTAL LABOUR CHARGES	:	\$	19,000.00	•





# ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 4150 C

S/N	NATURE OF JOBS			CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, DOOR HINGES, RHS WING MIRROR COVER, 2 DOOR HANDLES, RHS A-PILLAR, RHS B-PILLAR, RHS SILL PANEL, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	@	550 s	<b>₹5.5</b> 6,50 <b>0</b> .00	3025
14	TO RENEW RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N	۱ \$	520.00	320
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	1 \$	192.00	
	TOTAL LABOUR CHARGES	:	\$	29,652.00	=: - %0 = \$





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4150 C

#### **DAMAGED PARTS & PRICES**

			DAMAGED FART	Jarmels
5/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER ⊀	1	\$ 1,313.00	
2	FRONT FENDER RIVET 🗡	3	\$ 12.00	
3	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 34.00	
4	FRONT FENDER INSULATION - RH 🗡	1	\$ 51.00	
5	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 39.00	
6	FRONT WHEEL HOUSING LINER - RH	1	\$ 198.00	
7	FRONT SIDE PANEL - RH	1	\$ 3,886.00	
8	FRONT DATA TAG	1	\$ 545.00	
9	FRONT TYRE PRESSURE DATA PLATE	1	\$ 45.00	
10	FRONT WINDOW HEATED	1	\$ 850.00	
11	FRONT QUARTER WINDOW - RH	1	\$ 653.00	
12	WINDOW PRIMER M	2	\$ 47.00	
13	REAR FUEL FILLER FLAP ?	1	\$ 102.00	
14	FRONT WHEEL HOUSING LINER - RH	1	\$ 281.00	
15	FRONT WHEEL SPOILER - RH	1	\$ 34.00	
16	Lea /	1	\$ 3,269.00	
17		1	\$ 189.00	
18	7	1	\$ 361.00	
19	7	1	\$ 99.00	
20	/	1	\$ 51.00	
	SUB TOTAL SPARE PARTS	:	\$ 12,059.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED





### MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4150 C

#### **DAMAGED PARTS & PRICES**

			Drill Wilder Fried	
5/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
	7			
21	FRONT DOOR HINGE HALVES - RH UPPER -	1	\$ 56.00	
22	FRONT DOOR HINGE HALF UPPER PART - RH LOWER	1	\$ 54.00	
23	FRONT DOOR HINGE HALF LOWER PART - RH LOWER	1	\$ 57.00	
24	FRONT DOOR INNER SEAL	1	\$ 189.00	
25	FRONT DOOR OUTER HANDLE WITH SENSOR - RH 7	1	\$ 187.00	
26	FRONT DOOR HANDLE TRIM PLATE - RH	1	\$ 246.00	
27	FRONT DOOR CAP - RH 514	1	\$ 39.00	
28	FRONT DOOR LOCK CYLINDER HOUSING - RH	1	\$ 543.00	
29	FRONT DOOR UNDERLAY - RH FRONT	1	\$ 7.00	
30	FRONT DOOR UNDERLAY - RH REAR	1	\$ 8.00	
31	FRONT DOOR MOUNTING BAR - RH 7.	1	\$ 180.00	
32	FRONT DOOR BOWDEN CABLE	1	\$ 64.00	
33	FRONT EXTERIOR WING MIRROR MOUNTING - RH Sal	1	\$ 726.00	
34	~	1	\$ 811.00	
35	· · · · · · · · · · · · · · · · ·	1	\$ 190.00	
36	TOTAL TOTAL DIL N	1	\$ 58.00	
37	TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL	1	\$ 274.00	
38		1	\$ 314.00	
39	FRONT WINDOW GUIDE - RH	1	\$ 314.00	
40	FRONT PILLAR B TRIM - RH	1	\$ 133.00	
	SUB TOTAL SPARE PARTS	:	\$ 4,450.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED





### MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4150 C

#### **DAMAGED PARTS & PRICES**

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT WINDOW APERTURE SEAL - RH INNER .	1	\$ 106.00	
42	FRONT DOOR WINDOW - RH 7	1	\$ 175.00	
	FRONT DOOR LOCK - RH ?	55(1		
43	The Association and Associatio	1	\$ 490.00	
44	FRONT DOOR STRIKER 7	1	\$ 117.00	
45	FRONT WINDOW REGULATOR - RH	1	\$ 266.00	
46	FRONT WINDOW REGULATOR MOTOR - RH	1	\$ 354.00	
47	FRONT DOOR CONTROL UNIT - RH 7	1	\$ 449.00	
48	FRONT DOOR TRIM - RH 7	1	\$ 2,279.00	
49	FRONT DOOR WIRING SET ?	1	\$ 648.00	
50	FRONT DOOR TRIM PANEL WIRING HARNESS .	1	\$ 169.00	
51	REAR DOOR Suc	1	\$ 2,609.00	
52	REAR DOOR OUTER SEAL - RH AL	1	\$ 189.00	
53	REAR DOOR ATTACHMENT PARTS 7.	1	\$ 283.00	
54	REAR DOOR CATCH 7	1	\$ 99.00	
55	/	1	\$ 51.00	
56	7	1	\$ 51.00	
57	- UNIT HODED DART BULLOWER	1	\$ 54.00	
58	THE PART BUILDINGS	1	\$ 57.00	
59		1	\$ 189.00	
60	- CHEST STUGGE BY	1	\$ 187.00	
	SUB TOTAL SPARE PARTS		\$ 8,822.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4150 C

#### **DAMAGED PARTS & PRICES**

5/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	REAR DOOR HANDLE TRIM PLATE - RH	1	\$ 246.00	
62	REAR DOOR HOUSING - RH 7	1	\$ 59.00	
63	REAR DOOR HANDLE BASE - RH 7	1	\$ 183.00	
64	REAR DOOR BOWDEN CABLE	1	\$ 96.00	
65	REAR DOOR LOCK - RH	1	\$ 703.00	
66	REAR DOOR STRIKER X	1	\$ 117.00	
67	REAR WINDOW REGULATOR - RH	1	\$ 266.00	
68	REAR WINDOW REGULATOR MOTOR - RH	1	\$ 332.00	
69	REAR DOOR CONTROL UNIT 7.	1	\$ 471.00	
70	7	1	\$ 314.00	
71	/	1	\$ 180.00	
72	TOTAL TOTAL TOTAL CTDID	1	\$ 333.00	
73	/ CUITOE DATI - PH	1	\$ 55.00	
74	ADERTURE SEAL - PHINNER	1	\$ 106.00	
7	X	1	\$ 139.00	
7	PUI <b>V</b>	1	\$ 168.00	
	7 REAR DOOR TRIM - RH ?	1	\$ 2,207.00	
	8 REAR DOOR WIRING SET 7	1	\$ 220.00	
	79 REAR DOOR TRIM PANEL WIRING HARNESS	1	\$ 103.00	
1	BO REAR DOOR WINDOW - RH	1	\$ 158.00	
	SUB TOTAL SPARE PARTS	:	\$ 6,456.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 4150 C

#### **DAMAGED PARTS & PRICES**

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
81	REAR ALUMINIUM RIM 3CO	1	\$	1,519.00	
82	REAR ALUMINIUM RIM RUBBER VALVE	1	\$	4.00	
83	ACRYLIC SEALANT N	S/N	\$	180.00	
84	CAVITY WAX	S/N	\$	140.00	
85	STONE CHIP ~/	S/N	\$	180.00	
86	METAL FILLER POWDER	S/N	\$	280.00	
87	REAR WINDSCREEN SEALANT	S/N	\$	200.00	
88	1/4 GLASS SEALANT	S/N	\$	100.00	
89	SUNDRIES ?		\$	700.00	
	TOTAL SPARE PARTS	1	\$	35,090.00	
	TOTAL LABOUR CHARGES	:	\$	29,652.00	
	GRAND TOTAL	:	\$	64,742.00	
			_		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

# **♦ PREMIUM** AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

**AUTHORISED DATE** 

**FXCESS COST** LIABILITY

REMARKS

PLEASE NOTE

(ASUL - HP90010068 12/01/23 @1545 16 days

excers: Tha

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER

LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer** 

Signature:

Date:

**10HNNY BOO BODY REPAIR MANAGER**  **ALLAN WU CLAIMS CONSULTANT**  \$\text{\$\sigma\_{1231}\$a0002 / PREMIUM AUTOMOBILES PTE LTD [408699]} \\
\text{\$\sigma\_{17}\$ PATE & TIME: 10/01/2023 17:06 (SGT)} \\
\text{\$\sigma\_{18}\$ POONG CHIN FONG (SGT))} \\
\text{\$\sigma\_{18}\$ POONG CHIN FONG (SGT))}

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

- 2. This Form must be completed by the Policyholder and/or the Actual Driver
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 10/01/2023 17:06 (SGT) Reported by Both Date of Accident 10/01/2023 08:15 (SGT) Exact Location of Accident KPE, Singapore KPE TOWARDS CITY BEFORE EXIT 9A Additional Location Information Country/State of Loss

#### **DETAILS OF OWN VEHICLE**

SNA4150C Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? JACQUELINE EMMA D/O CHARLES CHRISTIAN Name Of Registered Owner NRIC No SXXXX569D JACQUELINE\_EMMA@YAHOO.COM Email Address (Phone) +65-94377266 Mobile Phone No

Alternative Phone No

VEHICLE PARTICULARS

Audi Manufacturer A3 Model SEDAN 1.5 TFSI Variant

Exact purpose for which vehicle was being used at time of Private use accident

Are you claiming under your own insurance policy for repair to

Yes your vehicle? Vehicle Category Private car Transmission Auto CC 1498

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Policy Number / Cover Note Number 7210063619-01

DRIVER

Occupation

Name of Driver NRIC No Date Of Birth

JACQUELINE EMMA D/O CHARLES CHRISTIAN SXXXX569D 05/11/1981

• A consider D	
note Of Driving Pass	02/05/2000
ndvilla	02/05/2006
. Collus	16 YEARS AND 8 MONTHS Female
MODILO	(Phone) +65-94377266
AIL THORS THAT SEE	(Filone) +05-943//266
Ellian	IACOLIELINE EMMAGYALIOS SOLI
Addiese	JACQUELINE_EMMA@YAHOO.COM 198 DEPOT ROAD
Address complement	#12-37
Posicode	109693
is the driver the policyholder?	Yes
if No, Relationship of the Driver with the Insured	
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
474-748-7-758-8-7-7-8-8-7-7-8-7-8-7-8-7-8-7-8-	
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	V
Number of vehicles involved in the accident	Yes
	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	- Vee
Was any other vehicle or property damaged?	Yes 1
Number of Passengers (Including Driver)  Has the driver been approached by unknown person(s)	1
soliciting/offering accident claims assistance?	No
Translator's name	
Translator's ID	
Translator's phone number	*
Translator's email	
Original language used in the statement	
1 193 (1947) - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
FOREIGN VEHICLE 1	VP-0540D
Vehicle Registration Number	XD6549P
Vehicle Category	Goods vehicle
DETAILS OF POLICE ACTION	
THE PROPERTY OF THE PROPERTY O	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	•
n yoo, agama mom	
CIRCUMSTANCES OF ACCIDENT	
TURNING INTO THE LANE AND GOT HIT BY A LORRY FROM ONCE I SPOTTED ENOUGH SPACE. AS I WAS MERGING, I WDRIVER'S DOOR SIDE BY A LORRY.	THE BACK. WAS TURNING (MERGING INTO) THE RIGHT LANE VAS HIT ON MY RIGHT BACK DOOR, FOLLOWED BY THE
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Yes

Vehicle Registration Number Vehicle Manufacturer

XD6549P Volvo



Was there any video captured by Car Camera?

whicle Model	
hicle Variant	FMX
Vehicle Colour	=
vehicle Category	White
Name of Driver	Goods vehicle
Contact Number	RAJAGOPAL EZNILARESA
Address	(Phone) +65-83494910
Address complement	•
Postcode	-
Insurance Company Name	•
Nature Of Damage	•
Details of property damaged in accident	•
No. Of Passenger (Including Driver)	•
merading Driver)	

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use a sclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any research government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me
- (w) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of enveloperatinal packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

Policyholder's Signature / Date & Time 11.15 GM

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

R = XD (549P

Jurning into lane o	and got mit by a long from -	
	go wit by a long from	the beat.
Nas turning (men	A	
J	ing the right lane once	I spotted en ush
space B I was	marging I was hit o	
	marging, I was hit o	n my right
back dar follow	ed by drive down side in	1,
	to by done down side b	4 a lorry
	The second secon	
	The second of th	
The state of the s		
The second secon		
		•••
	2000	
Declaration		
We declare the foregoing particular	e are to a in every run root	
seciale the foregoing particular	s are must in every respect.	
		The state of the s
		10
		(4)
Jacques (stones)		<b>(P)</b>

Enquire PARF/COE Rebate for Registered Vehicle Vehicle Owner Particulars	
- Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	5690
Vehicle No.:	SNA4150C
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jan 2023
Vehicle Make:	AUDI AUDI AUDI AUDI AUDI AUDI AUDI AUDI
Vehicle Model:	A3 SEDAN 1.5 TFSI S TRONIC
Primary Colour:	Blue
Manufacturing Year:	2021
Engine No.:	DFY263535
Chassis No.:	WAUZZZGYXMA089991
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$27,237.00
Original Registration Date:	22 Jun 2021
First Registration Date:	22 Jun 2021
Transfer Count:	O The state of the
Actual ARF Paid: Intended PARF Rebate Details	\$15,132.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2031
PARF Rebate Amount: Intended COE Rebate Details	<b>\$11,349.00</b>
COE Expiry Date:	21 Jun 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,109.00
COE Rebate Amount:	\$50,742.00
Total Rebate Amount:	\$62,091.00
he information contained herein is correct as at 12 Jan 2023	

Tł

# Audi A3 Sedan Mild Hybrid 1.5A TFSI S-tronic

Price \$142,800			
Depreciation ⑦	\$16,190 /yr View models with similar depre	Reg Date	20-May-2021 (8yrs 4mths 7days COE left)
Mileage	16,000 km (9.7k /yr)	Manufactured ⑦	2021
Road Tax ②	\$684 /yr	Transmission	Auto
Dereg Value 🕜	\$59,872 as of today (change)	Fuel Type	Petrol-Electric
COE ⑦	\$58,089	OMV ②	\$27,236
Engine Cap	1,498 cc	ARF ②	\$15,131
Curb Weight ⑦	1,395 kg	Power	110.0 kW (147 bhp)
Type of Vehicle	Luxury Sedan	No. of Owners	1