

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAN	NCE BHD	R	Ref:	CS3/LPC22010728/Tqy3e2-1	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	D	Date:	29/03/2023	
			C	Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMN 7385R	Veh. Inspected		GBD 6085X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VP05/026479	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		13/01/2023	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN NV200 1.6A	c.c		1597	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	VM20058735	Colour		GREY	
	Odometer	188333 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	175/70 R14	ROADKING		6 mm	
	L/H Front Tyre	175/70 R14	ROADKING		6 mm	
	R/H Rear Tyre	175/70 R14	ROADKING		6 mm	
	L/H Rear Tyre	175/70 R14	ROADKING		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	26/10/2022	Inspection Date		31/10/2022	
	Survey held at	at 2 KAKI BUKIT AVENUE 2 #02-31 KAKI BUKIT AUTOHUB				
	Repairer	Repairer CHENG CHUAN MOTOR SERVICES				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					