



Service Request Details

Claim

S1M03NQP

Reference

CS/ASM23000454/p3 

Loss Date

3 December 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

7 Dec 2021 4:01:03 PM

Request Date

11 January 2023

Due Date

13 January 2024

Services

Re-inspection

Actions

Next Step

Finish the work

Complete Work

Vehicle Information

Incident Vehicle Registration #

FBT869G

Make

TPVD Yamaha

Model

NMAX 155 ABS CVT

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

CHONG Arnold

arnold.chongcs@axa.com.sg

Additional Instructions

Kindly conduct physical reinspection. Refer to email.

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message