



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23000455/Awy3e2 Date: 01/03/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 9332S	Veh. Inspected	SNG 9244B	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2300190/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	13/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	CITROEN C4 PICASSO	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF73A5GZTGJ834989	Colour	WHITE	
Odometer	85849 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	RYDANZ	6 mm	
L/H Front Tyre	215/50 R17	RYDANZ	6 mm	
R/H Rear Tyre	215/50 R17	RYDANZ	6 mm	
L/H Rear Tyre	215/50 R17	RYDANZ	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/01/2023	Inspection Date	13/01/2023	
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	