

(08/11/13) wef

ASS. REC. BY: John

REF:

CS/FCI 23 000494/Rg3

9
4612**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SM29256Dat Workshop m/s Volkswagenof 247, 1st & 2nd RdInsured: FCI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 161K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SM29256D Yr Regn: 2021 / MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Tiguan 1.4TSI C.C. 1395Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 27861 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG 222 SN ZLW 887380Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: _____

255/45R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 13/01/23D.O.I. 18/01/23

Survey held at

Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 83K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

TOTAL

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Commercial
Vehicles

Quotation

Non binding - Preview

Page

1/2

Company
SBS TRANSIT LTD
205 BRADDELL ROAD
COMFORT DELGRO
Singapore 579701

Customer Details:
Mr
BEFFERT
TORSTEN
90 ELIAS ROAD
#03-34
SINGAPORE 519950

Document no.
Document date 13-01-2023
Customer no. 5211001022
Customer GST-ID 199206653M
Dealer 30001
Job order number 2023001321/ 1
Job order date 13-01-2023
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMZ9256D	AD14N6R0	25-05-2021	WVGZZZ5NZLW887380	Tiguan R-Line 1.4 I TSI 110kW N6 DSG	13,694

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#6	280.00	302.40
5NA807421 GRU	Cover For Bumper Primed } <i>repair</i> REAR BUMPER (UPPER)	1	pcs.	1,728.77	#6	1,728.77	1,867.07
5NA807521C GRU	Spoiler Primed } <i>side</i> REAR BUMPER (CTR)	1	pcs.	606.15	#6	606.15	654.64
5NA807568C 041	Rear Diffusor Black } <i>side</i> REAR BUMPER (LOWER)	1	pcs.	600.57	#6	600.57	648.62
5NA919491A	Sensor Bracket	1	pcs.	15.49	#6	15.49	16.73
5NA919492A	Sensor Bracket	1	pcs.	15.49	#6	15.49	16.73
5NA919491	Sensor Bracket	1	pcs.	15.49	#6	15.49	16.73
5NA919492	Sensor Bracket	1	pcs.	15.49	#6	15.49	16.73
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	#6	84.64	91.41
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	#6	74.37	80.32
5NA853835 ZZZ	Decorative Moulding Brigh } <i>can</i> BUMPER LOWER MLDG CHROM (CTR)	1	pcs.	244.73	#6	244.73	264.31
5NA853841 ZZZ	Decorative Moulding Brigh } <i>can</i> BUMPER LOWER MLDG CHROM (LH)	1	pcs.	188.34	#6	188.34	203.41
5NA945105A	Reflector } <i>can</i> LHS REFLECTOR INNER	1	pcs.	86.53	#6	86.53	93.45
5NA945103	Reflector } <i>??</i> LHS REFLECTOR OUTER	1	pcs.	86.53	#6	86.53	93.45
5NA807393A	Guide Piece } <i>??</i> LHR BUMPER BRACKET (UPPER)	1	pcs.	62.31	#6	62.31	67.29
5NA807394A	Guide Piece } <i>?? X</i> RHR BUMPER BRACKET (UPPER)	1	pcs.	62.31	#6	62.31	67.29
5NA807393	Guide Piece } <i>??</i> LHR BUMPER BRACKET (SIDE)	1	pcs.	62.31	#6	62.31	67.29
5NA807394	Guide Piece } <i>X</i> RHR BUMPER BRACKET (SIDE)	1	pcs.	62.31	#6	62.31	67.29
	LABOUR	3	pcs.	840.00	#6	2,520.00	2,721.60
	SPRAY PAINT	2	pcs.	800.00	#6	1,600.00	3,456.00
	SBS DIRECT SETTLEMENT						
	DOA: 13/01/2023						
	TP VEH: SG5904Y						
	SURVEY BY:						

Quotation valid till 20-01-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	760.00	9,731.83	8%	839.35	10,491.83	11,331.18
Total	760.00	9,731.83		839.35	10,491.83	11,331.18

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road

Singapore 159934

Biz. Reg. No.: 199101494Z

GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
SBS TRANSIT LTD
205 BRADDELL ROAD
COMFORT DELGRO
Singapore 579701

Customer Details:
Mr
BEFFERT
TORSTEN
90 ELIAS ROAD
#03-34
SINGAPORE 519950

Document no.
Document date 13-01-2023
Customer no. 5211001022
Customer GST-ID 199206653M
Dealer 30001
Job order number 2023001321/ 1
Job order date 13-01-2023
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SMZ9256D	AD14N6R0	25-05-2021	WVGZZZ5NZLW887380	Tiguan R-Line 1.4 I TSI 110kW N6 DSG	13,694

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
----------	--------	----------	-------	-----	------------------------	------------------------

Approx 3 working days

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasm
Hg 80010068
4 days
18/01/23 @ 1500
Resy before print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Foreign Identification Number
Owner ID:	461R
Vehicle No.:	SMZ9256D
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jan 2023
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TIGUAN 1.4 TSI R-LINE
Primary Colour:	Grey
Manufacturing Year:	2020
Engine No.:	CZDB09677
Chassis No.:	WVGZZZ5NZLW887380
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$33,763.00
Original Registration Date:	25 May 2021
First Registration Date:	25 May 2021
Transfer Count:	0
Actual ARF Paid:	\$39,269.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 May 2031
PARF Rebate Amount:	\$29,451.00
COE Expiry Date:	24 May 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,089.00
COE Rebate Amount:	\$48,485.00
Total Rebate Amount:	\$77,936.00

The information contained herein is correct as at 19 Jan 2023

OK

Volkswagen Tiguan 1.4A TSI R-Line Panoramic Roof

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$169,800****Depreciation** ⓘ

\$17,200 /yr

[View models with similar depre](#)**Reg Date**

14-Oct-2021

(8yrs 8mths 24days COE left)

Mileage

19,000 km (15k /yr)

Manufactured ⓘ

2020

Road Tax ⓘ

\$624 /yr

Transmission

Auto

Dereg Value ⓘ\$78,870 as of today ([change](#))**OMV** ⓘ

\$33,661

COE ⓘ

\$64,700

ARF ⓘ

\$39,126

Engine Cap

1,395 cc

Power

110.0 kW (147 bhp)

Curb Weight ⓘ

1,660 kg

No. of Owners ⓘ

1

Type of Vehicle

SUV