

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY

Policy No:

Vehicle Reg. No.:

Party At Fault:

SHA1514C

UNKNOWN

Ref. No:

Date of Loss:

15/01/2023

Driveable?

NO

Make/Model:

HYUNDAI I40, 1.7 D CRDI F/L ABS
AIRBAG 4DR (A)

Vehicle Colour:

BLUE

Engine No:

D4FDEU461314

Odometer:

712865 KM

Vehicle Reg. Date:

19/05/2016

Gen Condition:

GOOD

Chassis No:

KMHLB41UMGU089704

Paint Type:

List Item Discount:

20.00 %

Total Loss?

NO

Est. Duration of Repair
(day)

6

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	6,223.72
Miscellaneous Items	11.00
Labour	1,820.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$\$) 8,054.72

+ GST 8.00% (\$\$) 644.38

Nett Amount (\$\$) 8,699.10

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan '2023)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHA1514C/16/01/2023 15:39	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	20.00	0.00 <i>R</i>	*1,052.20 FL <i>Scr</i>
2	1		*FRONT BUMPER BRACKET LH	20.00	0.00 <i>/</i>	*49.20 FL <i>Cr</i>
3	1		*FRONT BUMPER GRILLE LH	20.00	0.00	*187.20 FL <i>2xNW</i>
4	1		*FRONT FENDER LH	20.00	0.00 <i>/</i>	*663.00 FL <i>Bul</i>
5	1		*FRONT FENDER SHIELD LH	20.00	0.00	*174.90 FL <i>2xNW</i>
6	1		*FRONT WING MIRROR ASSY LH	20.00	0.00 <i>/</i>	*760.00 FL <i>Cr</i>
7	1		*FRONT DOOR PANEL LH	20.00	0.00 <i>/</i>	*2,707.70 FL <i>Bul</i>
8	1		*FRONT WHEEL COVER LH	20.00	0.00 <i>/</i>	*217.20 FL <i>Cr</i>
9	1		*FRONT WHEEL KNUCKLE LH	20.00	0.00	*552.00 FL <i>2xNW</i>
10	1		*FRONT WHEEL HUB W/ BEARING LH	20.00	0.00	*673.20 FL <i>2xNW</i>
11	1		*FRONT STRG TIE ROD LH	20.00	0.00	*125.20 FL <i>2xNW</i>
12	1		*FRONT STRG BALL JOINT LH	20.00	0.00	*73.10 FL <i>2xNW</i>
13	1		*FRONT SHOCK ABSORBER LH	20.00	0.00	*342.20 FL <i>2xNW</i>
14	1		*FRONT SHOCK ABSORBER MTG LH	20.00	0.00	*108.80 FL <i>2xNW</i>
15	1		*FRONT DOOR COMFORT STICKER	0	0.00	*75.00 FS <i>NEL</i>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,760.90
- List Item Discount on L Items (S\$)	1,537.18
Total Parts (S\$)	6,223.72

ComfortDelGro Engineering Pte Ltd/SHA1514C/16/01/2023 15:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

$$P = 4397.1$$

$$20\% = 879.42$$

$$= 3517.70$$

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	750.00 6.00
2	SPRAY PAINTING	New	800.00 7.50
3	REMOVE/REFIX FRONT UC SUSPENSION.	New	120.00 XNN
4	CHECK LIGHTING & WIRING	New	60.00 30
5	RESET FRONT WHEEL ALIGNMENT	New	90.00 XNN
Gross Labour Cost (\$\$)			1,820.00

ComfortDelGro Engineering Pte Ltd/SHA1514C/16/01/2023 15:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4 days 1 hr

$$T = 4983.70$$
$$207_u = 996.70$$
$$T = 3987$$

L/S 17/1/23
12pm

 ≈ 4000

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To replace damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modifications are allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: