

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No. 199607	198R GST Reg. No. 1	9-9607	190-K	
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	Ref:	CS/AGI23000564/Aqy3m4	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	С	ate:	23/06/2023	
			C	Code:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLG 6826R	Veh. Inspected		SLH 5845L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10019886 /JM	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		17/01/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JTDGG20W00J006160	Colour		WHITE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65R15	YOKOHAMA		6 mm	
	L/H Front Tyre	195/65R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	195/65R15	YOKOHAMA		6 mm	
	L/H Rear Tyre	195/65R15	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	15/01/2023	Inspection Date		17/01/2023	
	Survey held at RYDER AUTO PTE LTD					
		2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	1-)	Estimate Days of Repair				

15 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: