

(08/11/13) wof
ASS. REC. BY: Rama

REF: CS/SMR 23 000 565 / Ray 3

8514

COE - 2015 APR

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKS 2951L
 at Workshop m/s CYCLE & CARRIAGE
 of 188, PANDAN LUMPUR
 Insured: SMR
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKS 2951L Yr Regn: 2015 / APR
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MERCEDES BENZ GLA 200 S/R c.c 1995
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: 112415 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDC156943270 20338
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: 64K
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

N/S	O/S

Tyre Size: F: 235/45R19
 R: _____
 BS / DUN / EXNOVA GV / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 11/01/23 D.O.I. 06/02/23
 Survey held at CYCLE & CARRIAGE (PL)
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
REPAIR LIMIT - 3WK

We will be advising our principal a cost of repair P/P \$10,083.57 /-
 with 05 days of repair, subject to their approval.
 (red, \$5444.87, 35%)

Date/Time, File Pass to? : Prell. Report
 : Final Report
 1) 24/02/23
 Date/Time, File Return to?
 2) _____
 Report Format :
 Lump Sum / I.B.I: (\$) 10083.57)

Days Of Repair: 5
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____
) \$ + RS _____
) Photos _____
) Others _____
) _____

TOTAL



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKS2951L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information

WIP No 62461
Reg No/Reg Date SKS2951L / 02/04/2015
Date In/Mileage / 0
Chassis No WDC1569432J020338
Engine No 27091030414724
Make/Model MB/GLA 200 B/E OFFROADER (X1
Colour/Trim 027 761 Polar Silv/ 046 651 DINAMICA/AR

SKS2951L

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	17/01/2023/ 11:15	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : 2100407769-07 // 11/01/2023 DRIVE IN/TP VEHICLE NO. : 17/01/2023 // SHB1801T - FIRST CAPITAL DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				1920.00
A BPIRES RESPRAY RH/ FRONT DOOR, RH/ REAR DOOR & RH/ REAR FENDER				1600 3000.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.NETT			0.05	800.00
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				X 540.00
S BPN SUB TRANSFER RIM AND BALANCING TYRE. NETT PURCHASE ORDER NO:				60.00
M RH/ FRONT DOOR bt	1.00	2111.02	00.00	2111.02
M RH/ FRONT DOOR SEAL ne	1.00	317.72	00.00	317.72
M RH/ FRONT DOOR ORNAMENTAL MOLDING ne	1.00	123.46	00.00	123.46
M RH/ FRONT DOOR ABSORBING ne	1.00	74.42	00.00	74.42
M RH/ FRONT DOOR TRIM STRIP ?	1.00	207.96	00.00	207.96
M RH/ REAR DOOR bt	1.00	2274.37	00.00	2274.37
M RH/ REAR DOOR SEAL ne	1.00	317.72	00.00	317.72
M RH/ REAR DOOR ORNAMENTAL MOLDING ne	1.00	149.84	00.00	149.84
M RH/ REAR DOOR ABSORBING ne	1.00	74.42	00.00	74.42
M RH/ REAR DOOR GUARD PLATE X	1.00	36.44	00.00	36.44
M RH/ REAR DOOR ORNAMENTAL TRIM same?	1.00	194.99	00.00	194.99
M RH/ REAR DOOR 3/4 WINDOW X	1.00	152.25	00.00	152.25

Confirmed & accepted by

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

ESTIMATE FOR SKS2951L

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR 8500111 X

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information
WIP No: 62461
Reg No/Reg Date: SKS2951L / 02/04/2015
Date In/Mileage: / 0
Chassis No: WDC1569432J020338
Engine No: 27091030414724
Make/Model: MB/GLA 200 B/E OFFROADER (X1)
Colour/Trim: 027 761 Polar Silv/ 046 651 DINAMICA/AR

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	17/01/2023/ 11:15	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH/ REAR DOOR ORNAMENTAL TRIM	1.00	341.69	00.00	341.69
M RH/ RUNNING BOARD X	1.00	341.69	00.00	341.69
M RH/ RUNNING BOARD BRACKET X	1.00	81.68	00.00	81.68
M RH/ RUNNING BOARD BRACKET X	1.00	78.54	00.00	78.54
M RH/ REAR FENDER WHEEL ARCH TRIM <i>scu</i>	1.00	262.62	00.00	262.62
M RH/ REAR SPOKE WHEEL X	1.00	1633.61	00.00	1633.61

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Panel
Hp 90014068
5 days
R 06/02/23 @ 12:00
Resy before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirmed & accepted by

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Nett	15,474.44
8% GST on	1237.96
Total Payable	16,712.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seat or other repair requiring the removal of the windscreen.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 851H

Vehicle Details

Vehicle No.: SKS2951L

Vehicle to be Exported: No

Intended Deregistration Date: 12 Feb 2023

Vehicle Make: MERCEDES BENZ

Vehicle Model: GLA200 (R19 BI SR)

Primary Colour: Silver

Manufacturing Year: 2014

Engine No.: 27091030414724

Chassis No.: WDC1569432J020338

Maximum Power Output: 115.0 kW (154 bhp)

Open Market Value: \$31,725.00

Original Registration Date: 02 Apr 2015

First Registration Date: 02 Apr 2015

Transfer Count: 0

Actual ARF Paid: \$26,415.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 01 Apr 2025

PARF Rebate Amount: \$15,849.00

Intended COE Rebate Details

COE Expiry Date: 01 Apr 2025

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$76,790.00

COE Rebate Amount: \$16,411.00

Total Rebate Amount: \$32,260.00

Mercedes-Benz GLA-Class GLA200

Overview

Financial

Accessories

Similar

Research

Photos

Map



Think One Automobile



Price

\$60,800

Depreciation

\$24,490 /yr

[View models with similar depre](#)

Reg Date

02-Feb-2015

(1yr 11mths 20days COE left)

Mileage

88,172 km (11k/yr)

Manufactured

2014

Road Tax

\$740 /yr

Transmission

Auto

Dereg Value

\$28,586 as of today (change)

OMV

\$30,693

COE

\$75,289

ARF

\$24,971

Engine Cap

1,595 cc

Power

115.0 kW (154 bhp)

Curb Weight

1,435 kg

No. of Owners

2