

(08/11/13)

wef

ASS. REC. BY: PM

REF:

CC4/11123000580/Rpa3

105F

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SNE 718Xat Workshop m/s PERFORMANCEof 203, Alexander RdInsured: 111

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 140K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 70KVeh No: SNE 718X Yr Regn: 2021 7 NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 1162 HL LUX c.c. 1499Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 14249 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA7K 120707K24334Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 10/01/23D.O.I. 17/01/23Survey held at PERFORMANCEDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

16 JAN 2023

Estimate No. : b1 64643
Date Estimated : 10/01/2023
Prepared By : Yap Mee Key

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Chen Yanquan, Linus
Apt Blk 95A Henderson Road
#09-04
Singapore 151095

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNE718X	WBA7K120707K24334	30/11/2021	116i Hatch	9628

DESCRIPTION

To replace front grille and attachments.

To sticker wrapping front grille and LHS grate trim.

Sundries.

To supply front emboss number plate. 4-

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Labour 1:

VALUE
8.50
8.50 2,550.00
?
300.00
40.00
83.00

2,973.00

DESCRIPTION

C CLIP FOR PLASTIC NUT

LH SIDE TRIM GRILLE (LUXURY)

LH GRID LATERAL (LUXURY/SPORT)

SUPPORT NUMBER PLATE ECE

FRONT GRILLE (LUXURY)

QTY	PRIC	VALUE
10	1.10	11.00
1	96.95	96.95
1	113.10	113.10
1	76.75	76.75
1	710.05	710.05

Total Parts :

1,007.85

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 17/01/23 @ 1400 Excess S\$

Surveyor's Name RASUK Sign

Surveyor's Tel 900 100 68 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

Days Recommend 2 days



Labour 1	:	2,973.00
Parts	:	1,007.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	318.47
Grand Total	:	4,299.32



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	11/01/2023 18:49 (SGT)
Reported by	Both
Date of Accident	10/01/2023 14:08 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	25 KALLANG AVENUE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNE718X
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHEN YANQUAN LINUS
NRIC No	SXXXX105F
Email Address	thelinushabit@gmail.com
Mobile Phone No	(Phone) +65-90074570
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	116i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1499

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	SD21V17466/PC2/R00

DRIVER

Name of Driver	CHEN YANQUAN LINUS
NRIC No	SXXXX105F
Date Of Birth	25/10/1988
Occupation	Indoor

Date Of Driving Pass	13/04/2009
Driving experience	13 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90074570
Alt. Phone Number	-
Email Address	thelinushabit@gmail.com
Address	95A HENDERSON ROAD #09-04
Address complement	-
Postcode	151095
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACH

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD2069Z
Vehicle Manufacturer	Toyota
Vehicle Model	Noah
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	LIM BOON TIONG
NRIC No	SXXXX026C

Contact Number

Address

Address complement

Postcode


Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

-
-
-
-
-
-
-
-




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was the 2nd car behind from Taxi SHD20692 at the carpark exit of 25 Kallang Avenue. The taxi reversed and crashed into my car SNE 718X. This happened on 10th Jan 2023, 2.03pm.

DECLARATION


I/We declare the foregoing particulars are true in every respect.


Police Officer's Signature

Date & Time: 10/1/2023 6pm


Driver's Signature
(If driver is not the policyholder)

Date & Time:


Reporting Officer's Signature
Name: [Signature]
NR OFFICER: 677444

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (a) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature

Date & Time: 1/12/2020 10:00 AM

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Report

Reporting Centre Personnel's Signature

Name: Yap Keng

NRIC/IN No: C127488811

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	105F
Vehicle No.:	SNE718X
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Jan 2023
Vehicle Make:	B.M.W.
Vehicle Model:	116I LED HL LUXURY
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	36746583B38A15A
Chassis No.:	WBA7K120707K24334
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$31,988.00
Original Registration Date:	30 Nov 2021
First Registration Date:	30 Nov 2021
Transfer Count:	0
Actual ARF Paid:	\$36,784.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2031
PARF Rebate Amount:	\$27,588.00
COE Expiry Date:	29 Nov 2031
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,000.00
COE Rebate Amount:	\$41,660.00
Total Rebate Amount:	\$69,248.00

The information contained herein is correct as at 18 Jan 2023

OK

BMW 1 Series 116i Luxury

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$132,888		
Depreciation [?]	\$13,820 /yr View models with similar depre	Reg Date	26-Apr-2021 (8yrs 3mths 7days COE left)
Mileage	12,975 km (7.5k /yr)	Manufactured [?]	2020
Road Tax [?]	\$684 /yr	Transmission	Auto
Dereg Value [?]	\$68,959 as of today (change)	OMV [?]	\$32,286
COE [?]	\$49,640	ARF [?]	\$37,201
Engine Cap	1,499 cc	Power	80.0 kW (107 bhp)
Curb Weight [?]	1,340 kg	No. of Owners [?]	1