

RECEBY: TP

REF:

NS/ INC 23000594/Tvp3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / VS / TPRES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop Tm/s _____
of _____
Insured: SMM 8199K
Policy No: _____
Claims No: MT/1205545-002
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Turn Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS WR
Date: _____ Person Contacted: Soly Vehicle: IN / OUT

Veh No: SM B1450M Yr Regn: 2014, Aug.
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: MAN NL320F c.c. 1058
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 564414 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WMIA A22228 E7 00269
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: NI / S/Rim / STD A/Rim or _____
Tyre Size: F: 275/70 R22.5
R: 225 (D)
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO, or Pirelli
Front _____ Rear _____
R/Bal. 8 mm R/Bal. 8/8 mm
L/Bal. 8 mm L/Bal. 8/8 mm
D.O.A. 13/1/2023 D.O.L. 17/1/23
Survey held at SMR WL
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP-INC-SMM 8199K
16/2/23	Final fig \$1316 confirmed by email (red 435,24%)

Site/Time, File Pass (o?) ☐ : Preli. Report
☐ : Final Report
Site/Time, File Return to?
16/2/23-typist
Report Format: TP
Turn Sum / I.E.R. / \$1316

Days Of Repair: 2
Resurvey No. of Trip: 1
Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:	
Transportation:	
S + RS	
Photos	
Others	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 17/01/2023

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB1450M
Case Reference Number	BUS/01/23/7008
Registration Date	8/7/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Yang QiuJun
Type of Accident	Side Swipe
Accident Date and Time	1/13/2023 6:50 PM
Accident Reported Date and Time	1/16/2023 11:41 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1450M - Right rear bumper scratched SMM8199K (TP) - Insured with Income
Prepared Date and Time	1/17/2023 10:04 AM
Chassis Number	WMAA22ZZ8E7002169
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$956.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,751.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date		
Signature		
Remarks		

02 days

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/01/2023

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR RHS PORTION	\$795.00	
Total Labour	\$795.00	530

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$956.00	786
Total Spray Painting & Panel Beating	\$956.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Tanji 97495749
 WP 17/1/23 @ 1030
 Resurvey after repair
 Tanji@ekhauto.com
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: