



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428		Ref: CS/LIP23000601/Uwy3m4 Date: 02/02/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GR 1488S	Veh. Inspected	SLK 1304S
Policy No.		Coverage (\$)	0.00
Claim No.	AVS23/0252	Excess (\$)	0.00
Assign From	ANDY SEAH	Assign Date	18/01/2023
2. Vehicle Particulars & Condition			
Make & Model	BMW 216D GRAN TOURER (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WBA2E320105B45687	Colour	GREY
Odometer	149335 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/50 R17	BRIDGESTONE	7 mm
L/H Front Tyre	215/50 R17	BRIDGESTONE	7 mm
R/H Rear Tyre	215/50 R17	BRIDGESTONE	7 mm
L/H Rear Tyre	215/50 R17	BRIDGESTONE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/01/2023	Inspection Date	17/01/2023
Survey held at	TLM AUTOMOBILE PTE LTD 1 DEFU LANE 6, DEFU INDUSTRIAL PARK A, SINGAPORE 539365		
5a. Remarks			
A)REGISTRATION DATE: 06 JAN 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	