

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC22008502/Dqy3e2-1	
	300 BEACH ROAD #17-04/07 THE CC	) NCOURSESINGAPORE 199555		Date:	31/01/2023	
				Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKP 4840B	Veh. Inspected		FBT 6677D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VP05/026200	Excess (\$)		0.00	
	Assign From	ENG HUEY NI	Assign Date		18/01/2023	
2.	Vehicle Particulars & Condition					
	Make & Model	CFMOTO 400GT	c.c		0	
	Engine No.	HIDDEN	Year of Reg.		2022	
	Chassis No.	LCEPESL53N6000159	Colour		BLUE	
	Odometer	3615 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	120/70Z R17	PIRELLI		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/70Z R17	PIRELLI		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	23/08/2022	Inspection Dat	е	01/09/2022	
	Survey held at	M 1 MOTORING	•			
		411 CHANGI ROAD SINGAPORE 419860				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		3 Work	ing Days	