ASS. FILE BY: REF: CS/FCI23000649/Any3m4

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLN 2592D. Yr Regn: 2017, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Fit c.c 1317

Colour Bronze A/C: Insured / Std / NI / NA

Sp.Reading 179026 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GK31216501

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15.

R: 195/55R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	08/02/23.

Survey held at Jack Cars.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap.
	Adrian confirmed lump sum: $1,500 and 3 days
	MV : (red, $2530, 63%)
	PV :
	Nett :
	161E.

Date/Time, File Pass to? ☐ : Preli. Report

1) 20/04/23 ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Inve ($)

Survey Fee:	135
Transportation:	50
___S + RS___SI	50
Photos	31
TOTAL:	266