

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22005740/Rvy3m4	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	21/06/2022	
	ATTN: ONG KIAN	THENG DERICK		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKB 3399P	Veh. Inspected		FY 129K	
	Policy No.	P1636007	Coverage (\$)		0.00	
	Claim No.	S2M0440F	Excess (\$)		0.00	
	Assign From	ONG KIAN THENG DERICK	Assign Date		16/06/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA WAVE 125I A	c.c		125	
	Engine No.	HIDDEN	Year of Reg.		2004	
	Chassis No.	NF125MS0006186	Colour		MULTI	
	Odometer	99999 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	70/80-17	MAXXIS		3 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	70/80-17	MAXXIS		3 mm	
	L/H Rear Tyre				mm	
4.	•	Description of Damages				
	THE VEHICLE SUS	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information					
	Accident Date	11/06/2022	Inspect Date / T	ime	16/06/2022 (03:35 PM)	
	Survey held at	SPEEDY MOTOR CYCLE SERV	ICE CENTRE			
	BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$1,500					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM22005740/Rvy3m4

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

DECD And Computer OAE Linear LAnguage

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$