

REF: CS3/ASM22001687/Rnp3-1

Special Instruction:

HENG XINYI (SEAH ONG) HSP ASSIGNMENT (Office)

L/SUM: 6.300 / REPAIR : 7 DAYS

From (Person): ~~KHONG LYNN~~ of ~~ACM~~ Date/Time: 11/01/2023

Third Parties:

Estimated Cost: _____ Bill to: _____

Claimant:

Surveyor: AEON AUTO CONSULTANT LLP

Workshop: V8 MOTOR WERKZ PTE LTD

OD/ **Pre-inspection** / Evaluation

To Inspect Vehicle No: SFS 292C Insured: SHD 8851S

at Workshop m/s V8 MOTOR WERKZ PTE LTD

Tel:

of ~~0-01N MINO INDUSTRIAL ESTATE 0-01N MINO INDUSTRIAL ESTATE~~

~~SINGAPORE 575811 70 TUAS SOUTH AVENUE 1 SINGAPORE 637285~~

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 07/02/2022
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 21/04/23 Confirmed with _____ Final Fig _____, ____ days (Red \$ ____/____%; Original ____ days)

Date/Time: 21/04/23 Submit Final Fig 2650, 4 days (Red \$ 3650 / 58 %; Original 7 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

Transport

Photos

Others

Total

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____