

ASS. REG. BY: _____ REF: _____

REF: CS3/SPP23000716/Say3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SFF
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SAP2593A Yr Regr: 9/NOV/2016
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota altis CC: 1.598
 Colour: Dark grey AC: Insured / Std / NI / NA
 Sp. Reading: 257350 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MFO53REH104556251
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NI / S/Rim / STD A/Rim; or

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$54K
 IDAC Accident Rpt: _____ Consistent? Yes or No
 GIA / PR Sect: _____ Consistent? Yes or No
 Est. Repairs: 12 days Rate: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

N/S	O/S
N/S	O/S

Tyre Size: F: 215 / 45 R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LZA / M/C / OHTSU / PIR / SUMI /
 TOYO / YOKO or Go Form
 Front R/Bal. 5 mm Rear R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 7/01/23 D.O.I. 26/1/23 12m
 Survey held at Apex motoring
 Des. of Damages: FR / Rear / O/S / N/S / UC / Rooftop or
 The UC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Balance: 45.8m
	yearly: 13K
	mv: 54K
	NV: 23K
<u>21/7/23</u>	Submit Damage Assessment Report. (LS \$14900/-; 12 days) (check items: \$233.25) (The estimated range is \$14900 to \$21,500)

Date/Time, File Pass to? : Prell. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____
 Report Format: DAR
 Lump Sum / I.B.J: (\$ 14900/-)

Days Of Repair: 12
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	\$ + RS. 1.5
Photos:	
Other:	
TOTAL:	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	882D
Vehicle Details	
Vehicle No.:	SGP2593A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Apr 2023
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZR589677
Chassis No.:	MR053REH104556251
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,990.00
Original Registration Date:	09 Nov 2016
First Registration Date:	09 Nov 2016
Transfer Count:	1
Actual ARF Paid:	\$19,990.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Nov 2026
PARF Rebate Amount:	\$12,993.00
Intended COE Rebate Details	
COE Expiry Date:	08 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$18,328.00
Total Rebate Amount:	\$31,321.00

The information contained herein is correct as at 04 Apr 2023

OK

Post an Advertisement
 Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Low Interest Rate In-House Loan by GV Cars Financing



Drive into the festive season with 3.28% p.a. by GV Cars Financing!
 GV Automobile Centre [StarAd](#)

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Sort by results/page

18 vehicles

[Advanced Search](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Corolla Altis 1.6A	Any	Any	2016	Any	Any	Any	Available
	Toyota Corolla Altis 1.6A Classic	\$54,800	\$13,870 /yr	08-Aug-2016	1,598 cc	-	Sedan	Available
Well Maintained, Wear And Tear Done. Trade In Welcome. Bank / Flexible Loan Options Available. WhatsApp Or Call Now For Viewing!								
Posted: 02-Apr-2023								
	Toyota Corolla Altis 1.6A Elegance	\$58,800	\$15,580 /yr	27-May-2016	1,598 cc	150,000 km	Sedan	Available
\$0 downpayment, 100% loan available. Free 1 year warranty, free 1 servicing, free pre-purchase check, free full car grooming before ha... PREMIUM AD								
Posted: 02-Apr-2023								
	Toyota Corolla Altis 1.6A Elegance	\$59,800	\$14,300 /yr	27-Sep-2016	1,598 cc	110,000 km	Sedan	Available
2 owners, Borneo agent unit, elegance model, rd tax till sep 2016 100% loan available, accident free, original paint, easy maintenance, s...								
Posted: 01-Apr-2023								
	Toyota Corolla Altis 1.6A Elegance	\$50,800	\$13,760 /yr	28-Mar-2016	1,598 cc	78,000 km	Sedan	Available
Fuel efficient, spacious interior and boot space. Ever reliable engine and gearbox, what more can you ask for? An excellent family sedan!...								
Posted: 01-Apr-2023								
	Toyota Corolla Altis 1.6A Elegance	\$60,688	\$14,490 /yr	03-Oct-2016	1,598 cc	103,000 km	Sedan	Available
2 owner only. 90% loan of the car price available.100% accident free. Super low mileage done at 15000km per year. Perfect gearbox, s...								
Posted: 01-Apr-2023								
	Toyota Corolla Altis 1.6A Classic	\$54,500	\$12,900 /yr	14-Oct-2016	1,598 cc	112,000 km	Sedan	Available
Well Maintained By Previous Owner, Wear And Tear Done Up, Good Fuel Consumption! All Trade-in Welcome! Attractive Financing Availa...								
Posted: 31-Mar-2023								

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 18/01/2023 10:47 (SGT)
Reported by Driver
Date of Accident 17/01/2023 11:00 (SGT)
Exact Location of Accident 9 Raffles Boulevard, Millenia Walk, #01-51, Singapore 039596
Additional Location Information RAFFLES BOULEVARD JUNCTION
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGP2593A

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner ASIA EXPRESS CAR RENTAL PTE LTD
Company Reg No 2XXXXX882D
Email Address PEIJIE@EXPRESSCAR.COM.SG
Mobile Phone No (Phone) +65-91998131
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model Corolla
Variant ALTIS 1.6 CVT
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1598

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited
Policy Number / Cover Note Number 5126469337

DRIVER

Name of Driver JEFFREY ANG HOCK PENG
NRIC No SXXXX688E
Date Of Birth 02/01/1964
Occupation Outdoor

Date Of Driving Pass	18/04/1985
Driving experience	37 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88008303
Alt. Phone Number	-
Email Address	PEIJIE@EXPRESSCAR.COM.SG
Address	BLK 221 BUKIT BATOK EAST AVENUE 3 #02-170
Address complement	-
Postcode	650221
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Hong Kah North Neighbourhood Police Post
Police Station Phone No	(Phone) +65-18005679999
Alt. Police Station Phone No	(Fax) +65-65652508
Police Station Address	Blk 370 Bukit Batok Street 31 #01-201 Singapore 650370
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN AND POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH TRAFFIC POLICE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	TP416M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Government
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	UNKNOWN
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	TP416M
Were seat belts worn?	No
Was this injured conveyed to hospital by ambulance?	Yes

WITNESS DETAILS

WITNESS 1

Name	Dheeraj
Phone	(Phone) +65-82332453
Email	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  Policyholder's Signature / Date & Time	  Driver's Signature (If driver is not the policyholder) / Date & Time	 Witnessed by Reporting Centre Personnel
--	--	--

Sketch Plan

Describe Circumstances of the Accident

On 17/01/2023 at 11:00am I was driving along Raffles Blvd towards Sinter direction. There was a TP officer controlling the traffic and my side was stationary waiting for the TP convoy to pass. After a while the officer controlling the traffic rode off. And the traffic light was green on my side. All vehicles started to move off. I drove off too, just right after I pass the divider the TP came stop suddenly in front of me that I didn't have time to brake. I crash head on to his side.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

(0)Shipped (09)Buckled (10)Broken (11)Necessary (12)Missing (13)Tom
 (14)Unconfirmed (15)Not Working

MOTOR CAR (Frt)

(1)Replace (✓) (2)Repair (X) (3)Check (M)
 (4)Not Consistent (NC)

9/11/2016 REH10

Vehicle No: SGP 2593A

Front Portion					Rear Portion						
NAC	INC	Item	CON	AC	Qty	NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	BT	/		1071	992205	Fuse Box			
1002	991887	Frt Number Plate Base	DIS	/	\$255N	1072	994011	Relay Box			529
1003	991889	Frt Number Plate Garnish			\$205N						380
1004	991300	Frt Bumper	BT	/	650	1073	995053	Wiper Washer Tank	DD	/	170
1005	992341	Frt Bumper Clips	NEC	/	40 SN	1074	995052	Wiper Washer Tank Motor			145
1006	991325	Frt Bumper Bracket				1075	990159	Alternator Assy			243
1007	991462	Frt Bumper Side Retainer @ 7000	DIS	/	2	1076	990160	Alternator Belt			
1008	991433	Frt Bumper Reinforcement	DD	/	398	1077	992688	Power Steering Pump			
1009	991318	Frt Bumper Beam				1078	992669	Power Steering Belt			
1010	991468	Frt Bumper Sponge	CRA	/	169	1079	994431	Power Steering Cooler Pipe			
1011	991427	Frt Bumper Protector				1080	992692	Power Steering Hose			
1012	991420	Frt Bumper Pad				1081	990010	ABS Pump Control Unit			
1013	991363	Frt Bumper Grille	CRA	/	1P1	1082	990427	Brake Master Pump Assy			
1014	991301	Frt Bumper Moulding				1083	990403	Brake Booster Pump Assy			
1015	991407	Frt Bumper Lower Spoiler				1084	991005	Engine Top Cover			129
1016	991438	Frt Bumper Sensor				1085	991011	Engine Under Cover	CRA	/	246
1017	995100	Frt LH Bumper Fog Lamp Cover	CRA	/	140	1086	990946	Engine Mounting			
1018	991355	Frt RH Bumper Fog Lamp Cover	CRA	/	140	1087	990949	Engine Mounting Frt			
1019	995079	Frt LH Bumper Fog Lamp			361	1088	990950	Engine Mounting LH			
1020	995080	Frt RH Bumper Fog Lamp			361	1089	990952	Engine Mounting RH			
1021	991793	Frt Grille	CRA	/	382	1090	990951	Engine Mounting Rear			
1022	991328	Frt Grille Emblem	CRA	/	99	1091	992234	Gear Box Mounting			
1023	991799	Frt Grille Chrome Moulding				1092	991520	Frt LH Chassis Member	BT R		
1024	991222	Frt Apron Panel				1093	991520	Frt RH Chassis Member	BT R		
1025	992013	Frt Support Panel	BT	/	997	1094	990728	Frt Vertical Cross Member			
1026	992025	Frt Support Panel Top Garnish Cover	DIS	/	167	1095	991863	Frt Lower Cross Member			
1027	992416	Horn				1096	995070	Frt LH Fender	BUC	/	699
1028	991277	Frt Brace Panel	BT	/	159	1097	995072	Frt LH Fender Inner Panel	DD R		
1029	995153	Frt LH Headlamp Assy	CRA	/	2950	1098	995147	Frt LH Fender Lamp Emblem	NEC	/	58
1030	991821	Frt RH Headlamp Assy	CRA	/	2950	1099	995148	Frt LH Fender Protector			
1031	995088	Frt LH Side Lamp				1100	991740	Frt LH Fender Inner Shield			159
1032	995089	Frt RH Side Lamp				1101	995179	Frt LH Mudflap			
1033	990248	Bonnet	BUC	/	1045	1102	995170	Frt LH Wheel Rim			
1034	991328	Bonnet Emblem				1103	994025	Frt LH Rim Cover			
1035	990287	Bonnet Lock				1104	995065	Frt LH Tyre			
1036	990285	Bonnet Insulator	BT	/	186	1105	995071	Frt RH Fender	BUC	/	699
1037	990273	Bonnet Flinge @ 86	DIS	/	195	1106	991739	Frt RH Fender Inner Panel			
1038	990261	Bonnet Damper	BT	/	172	1107	991744	Frt RH Fender Lamp Emblem	NEC	/	58
1039	990305	Bonnet Rubber				1108	991752	Frt RH Fender Protector	NEC	/	49
1040	990252	Bonnet Cable	DIS	/	95	1109	991740	Frt RH Fender Inner Shield			
1041	990311	Bonnet Stand			83	1110	991884	Frt RH Mudflap			
1042	990119	Air Con Condenser			66	1111	992087	Frt RH Wheel Rim			
1043	990122	Air Con Fan Assy	DD	/	507	1112	994025	Frt RH Rim Cover			
1044	990134	Air Con Suction Pipe (Low Pressure)	BT	/	211	1113	995065	Frt RH Tyre			
1045	990118	Air Con Suction Hose			455	1114	992093	Frt Windscreen Glass	CRA	/	1593
1046	990133	Air Con Discharge Pipe (High Pressure)			489	1115	992117	Frt Windscreen Rubber			
1047	990114	Air Con Discharge Hose				1116	992108	Frt Windscreen Moulding	NEC	/	158
1048	990149	Air Con Liquid Pipe				1117	992098	Frt Windscreen Sealant	NEC	/	50 SN
1049	995066	Air Con Receiver Drier				1118	991019	ERP Bracket	NEC	/	26 SN
1050	990111	Air Con Compressor Assy			2908	1119	991020	ERP Unit			
1051	995294	Air Con Belt				1120	992140	Frt Wiper Arm			
1052	995074	Radiator	DD	/	1699	1121	992142	Frt Wiper Blade			
1053	992738	Radiator Cowling	CRA	/	244	1122	995045	Wiper Panel Garnish	CRA	/	366
1054	992742	Radiator Fan Assy	CRA	/	191						
1055	992745	Radiator Fan Clutch	JM	/	394	1123	991126	Firewall Panel			
1056	992758	Radiator Hose Top	BT	/	85	1124	990753	Dashboard Assy			
1057	992757	Radiator Hose Bottom			69	1125	992282	Glove Box Cover			
1058	992741	Radiator Expansion Tank			275	1126	992281	Glove Box Compartment			
1059	990151	Air Duct	CRA	/	160	1127	994483	Steering Wheel Airbag			
1060	990070	Air Cleaner Assy			455	1128	994485	Steering Wheel Airbag Sensor			
1061	990056	Air Cleaner Hose			113	1129	990749	Dashboard Airbag			
1062	990089	Air Cleaner Resonator	CRA	/	271	1130	990750	Dashboard Airbag Sensor			
1063	991712	Frt Exhaust Manifold			822	1131	990029	Airbag Control Unit			
1064	991713	Frt Exhaust Manifold Cover				1132	990864	Frt Driver Seat			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)				1133	991922	Frt RH Seat Belt Assy			
1066	991714	Front Exhaust Pipe				1134	991899	Frt Passenger Seat			
1067	990219	Battery			220 SN	1135	995182	Frt LH Seat Belt Assy			
1068	990224	Battery Cover				1136	990247	Sticker			
1069	990223	Battery Bracket	BT	/	54			Frt LH Door	SCR R		
1070	990229	Battery Tray			89			" RH "	BT R		
								Clips	NEC	/	150 SN

No of Items: _____ Address: * Labour: - Pls see attached list.

Labour :

Veh. No.
SGP2593A

- | | |
|---|---------|
| 1) Replacing accident damaged parts, knock/jack & straighten accident affected areas. | \$1,000 |
| 2) Spray painting accident affected areas. | \$1,500 |
| 3) Carry out body cavity preservation on accident affected areas. | \$180 |
| 4) Checking electrical wiring & lighting system for proper function including focus headlamp | \$50 |
| 5) Replacing air con damaged parts including discharge, vacuum, re-charge freon gas & check for leak. | \$180 |
| 6) Removing & installing radiator assy including carry out pressure coolant test to check for leak. | \$150 |
| 7) Jack & straighten front chassis on O-Liner including measure according to specifications. | \$250 |
| 8) Replacing front windscreen including carry out water leak test. | \$120 |
| 9) Replacing fuse box, relay box, etc, including re-wiring at both boxes. | \$280 ? |