

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305543124
Date : 25.01.2023

FINALIZATION FORM

To : LKK

Fax :

Attn : IRFAN

Vehicle Reg No. : SHA2405C

Date of Accident : 14.01.2023

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: ALLIANZ --- SMV9577Z

2. The finalized amount shall be:

(a) Spare Parts after List discount _____

(b) Labour Charges (include advertisement stickers etc,if any) _____

Total for Part-By-Part Repair Cost _____

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$850.00

Final Lumpsum Repair cost \$850.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : *LIM TS*

Signature : _____

Name : LIM TS

Name : IRFAN

Tel : 62148398

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee / GEARS	\$26.75 / \$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:
