

ASS. REC. BY:

Smg

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: TMI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
11/11	

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Sect: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Date / Time	Action / Instruction
	L/S

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

☐ : Prell. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL _____

Veh No: Sh 75 7961m Yr Regn: 3d/10/19

Type: M.Car / M.Cyclo / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or _____

Make: Hyundai 101g c.c. 1580

Colour Blue AC: Insured / St / NI / NA

Sp. Reading 325772 T/Radio: Insured / St / NI / NA

Eng/No: _____

C/No: Km h 6851 CVLV188677

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim, or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 15/1/23

Survey held at Com Fort

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roodtop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear R/Bal. 5 mm
L/Bal. 5 mm
D.O.I. 17/1/23 12pm


Team: ARC Repair TP(CLS0)1 JOB CARD Sales Order: 5663975 JC NO.305542846

CUSTOMER MS TOMER NO RESS (R) (P) COUNT CARD NO.	COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755	REGN NO: SH 7961M	MILEAGE
		MAKE: HYUNDAI	FUEL E.....1/2.....F
		MODEL IONIQ(G3)	DATE/TIME IN 16.01.2023 15:35
		YR OF MANU 30.10.2019	TARGET DATE
		CHASSIS CODE KMHC851CVLU188677	COMPLETION DATE/TIME:

Accident Date: 15.01.2023
NATURE: 3P 15.01.2023

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 7961M YY

Vehicle No.: SH 7961M

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard