

ASS. REC. BY:


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 ON / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspcd Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: AIS
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 1/2 days Res: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SBS 607313 Yr Regn: 22 Aug 2011
 Type: M.Car / M.Cycle / Van / Lorry / Taxi / Prime Mover /
 Truck / Tractor or
 Make: Mercedes Bitano c.c. 7700
 Colour: Purple / White A/C: Insured / Std / NI / NA
 Sp. Reading: 893971 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WEB 62808323122063
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insured / Jammed / Leaked / Burnt or
 Brake: Insured / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD / Rim, or
 Tyre Size: F: 275 / 70 R22
 R: 235 / 70 R22
 DS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 8 mm R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. 17/1/23 D.O.I. 27/1/23
 Survey held at SBS Soon Lee
 Des. of Damages: Frt / Rear / CRS / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

Date/Time, File Return to?

1) _____
2) _____

Report Format:

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

SBS Transit Ltd.
Bus Engineering
JR Workshop

NOTIFICATION

BUS INFORMATION

Date: 19/01/2023

Bus Number: SBS6073B

Description: MB Citaro O530, SD, AC, 2 Axle

NOTIFICATION INFORMATION

Order # JR2301002176

OrderType: JAC1

SAP Order #

Description: SCH3DUL3 BACK: ACCIDENT SIDESWIPE HIT BY GARBAGE TRUCK, XD 6752T AT ALONG JURONG WEST AVENUE 1, ON 17/01/2023 AT 21:55HRS. BRAK3 & ST33RING-OK, RHS VIEW MIRROR GLASS CRACK..... SBS6073B, BC76329, Svc502.

Reported By: 0

Reported Date/Time: 19/Jan/2023 08:26

Notification Status:CB Call Back

NOTIFICATION DETAILS

S/N Symptom Description

Remarks: SBS6073B, BC76329, Svc502.

BC Name & Signature: _____

Goh Jit Min
Snr Technical Officer
Boon Lee Workshop

Date: 19/01/2023

mohamed ifan

90097659

27/1/23

lrfan@LKKAuto.com

4.3upn