

08/11/17

ASS. REG. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____
Insured: AIS

Policy No. _____

Claims No. _____

Sum Insured: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

GIA / PR Secn: _____

Est. Repairs: _____

Lum Sum: _____

Consistent? : Yes or No

Consistent? : Yes or No

Res: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBS 6073B Yr Regn: _____

Type: M.Gar / M.Cycle / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: mercedes citaro c.c. 7700

Colour purple / white

Sp. Reading 893971

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim, or

Tyre Size: F: 275 / 70 R 22

R: 235 / 70 R 22

BS / DUN / EXNOVA / GY / FS / LIZA / UIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 17/1/23

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 27/1/23

SBS Soon Lee

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS : \$ _____

Photos

Others

TOTAL

NOTIFICATION

BUS INFORMATION

Date: 19/01/2023

Bus Number: SBS6073B

Description: MB Citaro O530, SD, AC, 2 Axle

NOTIFICATION INFORMATION

Order # JR2301002176

OrderType: JAC1

X
Surveyor

893971.5 km

SAP Order #

Description: SCH3DUL3 BACK: ACCIDENT SIDESWIPE HIT BY GARBAGE TRUCK, XD 6752T AT ALONG JURONG WEST AVENUE 1, ON 17/01/2023 AT 21:55HRS. BRAK3 & ST33RING-OK, RHS VIEW MIRROR GLASS CRACK..... SBS6073B, BC76329, Svc502.

Reported By: 0

Reported Date/Time: 19/Jan/2023 08:26

Notification Status: CB Call Back

NOTIFICATION DETAILS

S/N Symptom Description

Remarks: SBS6073B, BC76329, Svc502.

BC Name & Signature: _____

Goh Jit Min
Snr Technical Officer
Boon Lee Workshop

Date: 19/01/2023

mohamed ifan

90097659

27/1/23

ifan@LKKAuto.com

4.3upn