

ASS. REC. BY:

REP:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLK2734C Yr Regn: 2017 / Jan.

Type: (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle. c.c. 1496

Colour: Silver. A/C: Insured / Std / NI / NA

Sp. Reading: 104594 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK81007748

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (In order) / Jammed / Leaked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 195/55R15

R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / (MIC) / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 26/01/23.

*Survey held at Kang.

Des. of Damages: (Front) / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Liberty.

MV: 601C

PV: 26K

Nett: 34K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Foot. Insp (\$ _____)

: S + RS. SI

Photos

Others

Report Format: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/01/2023 15:04 (SGT)
Reported by	Both
Date of Accident	14/01/2023 12:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	KPE TOWARDS ECP
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK2734C
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KATHERINE KOH POH CHOO @EER POH CHOO
NRIC No	SXXXX556B
Email Address	KATKOH77@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-97697187
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Shuttle
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5087398119-06

DRIVER

Name of Driver	TAN CHEW MENG @SNG CHEW MENG
NRIC No	SXXXX556D
Date Of Birth	31/08/1954
Occupation	Indoor

Date Of Driving Pass	01/04/1976
Driving experience	46 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97709252
Alt. Phone Number	-
Email Address	JMPASG1@YAHOO.COM.SG
Address	APT BLK 608 ELIAS ROAD
Address complement	#12-178
Postcode	510608
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	5
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	KATHERINE KOH POH CHOO
Gender	Female

PASSENGER 2

Name	JACINTHA TAN YANYI
Gender	Female

PASSENGER 3

Name	KOH SIEW HOON
Gender	Female

PASSENGER 4

Name	KENNETH TAN JUNYI
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Pasir Ris Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005852999
Alt. Police Station Phone No	(Fax) +65-65855261
Police Station Address	1 Pasir Ris Drive 4 #01-01 Singapore 519457
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT NO.: T/20230114/2111.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Reasons for not uploading a video of the accident WILL EMAIL TO INSURANCE.

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJE323Z
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver SUN RENWANG
 NRIC No SXXXX540D
 Contact Number (Phone) +65-97708547
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident VEHICLE B
 No. Of Passenger (Including Driver) -

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SDJ87A
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver HO BING HUI
 NRIC No SXXXX706C
 Contact Number (Phone) +65-97808040
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident VEHICLE C
 No. Of Passenger (Including Driver) -

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SFF1520G
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver ONG PO KENG
 NRIC No SXXXX723F
 Contact Number (Phone) +65-91826667
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -



Details of property damaged in accident
No. Of Passenger (Including Driver)

VEHICLE D

INJURED PERSONS DETAILS

INJURED 1

Name of injured person TAN CHEW MENG
Gender Male
Phone No (Phone) +65-97709252
Address
Address Complement
Post Code
Approximate Age Years Old
Injuries Sustained
Injured person in which vehicle? SLK2734C
Were seat belts worn? Yes
Was this injured conveyed to hospital by ambulance? No

INJURED 2

Name of injured person KATHERINE KOH POH CHOO
Gender Female
Phone No (Phone) +65-97697187
Address
Address Complement
Post Code
Approximate Age Years Old
Injuries Sustained
Injured person in which vehicle? SLK2734C
Were seat belts worn? Yes
Was this injured conveyed to hospital by ambulance? No

INJURED 3

Name of injured person JACINTHA TAN YANYI
Gender Female
Phone No
Address
Address Complement
Post Code
Approximate Age Years Old
Injuries Sustained
Injured person in which vehicle? SLK2734C
Were seat belts worn? Yes
Was this injured conveyed to hospital by ambulance? No

INJURED 4

Name of injured person KOH SIEW HOON
Gender Female
Phone No
Address
Address Complement
Post Code
Approximate Age Years Old
Injuries Sustained
Injured person in which vehicle? SLK2734C
Were seat belts worn? Yes
Was this injured conveyed to hospital by ambulance? No

INJURED 5

Name of injured person KENNETH TAN JUNYI
Gender Male
Phone No
Address
Address Complement
Post Code

Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLK2734C
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SECTION 1

SECTION 2

1. The first vehicle involved in the collision was a silver Mercedes-Benz SLK2734C, registration SLK2734C, driven by [Name], of [Address], [Postcode]. The vehicle was travelling in the [Direction] lane of the road at the time of the collision.

2. The second vehicle involved in the collision was a [Description of vehicle], registration [Registration], driven by [Name], of [Address], [Postcode]. The vehicle was travelling in the [Direction] lane of the road at the time of the collision.

3. The collision occurred on [Date] at [Time] on [Road Name] in [Location]. The weather was [Weather] and the visibility was [Visibility].

4. The collision occurred as the two vehicles were approaching each other from opposite directions. The silver Mercedes-Benz SLK2734C was travelling at approximately [Speed] mph and the [Description of vehicle] was travelling at approximately [Speed] mph.

5. The collision occurred as the two vehicles were approaching each other from opposite directions. The silver Mercedes-Benz SLK2734C was travelling at approximately [Speed] mph and the [Description of vehicle] was travelling at approximately [Speed] mph.

6. The collision occurred as the two vehicles were approaching each other from opposite directions. The silver Mercedes-Benz SLK2734C was travelling at approximately [Speed] mph and the [Description of vehicle] was travelling at approximately [Speed] mph.

7. The collision occurred as the two vehicles were approaching each other from opposite directions. The silver Mercedes-Benz SLK2734C was travelling at approximately [Speed] mph and the [Description of vehicle] was travelling at approximately [Speed] mph.

8. The collision occurred as the two vehicles were approaching each other from opposite directions. The silver Mercedes-Benz SLK2734C was travelling at approximately [Speed] mph and the [Description of vehicle] was travelling at approximately [Speed] mph.

9. The collision occurred as the two vehicles were approaching each other from opposite directions. The silver Mercedes-Benz SLK2734C was travelling at approximately [Speed] mph and the [Description of vehicle] was travelling at approximately [Speed] mph.

10. The collision occurred as the two vehicles were approaching each other from opposite directions. The silver Mercedes-Benz SLK2734C was travelling at approximately [Speed] mph and the [Description of vehicle] was travelling at approximately [Speed] mph.



Signature of [Name]

Signature of [Name]

SLK2734C
 2008
 2008
 2008

SLK2734C

2008
 2008
 2008

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



- A SLK 2734 C
- B SJE 323 Z
- C SDS 87 A
- D SFF 1520 G

Describe Circumstances of the Accident

I was driving along KPE towards ECP. My front vehicle slow down and stop. I also follow to slow down and stop. The car behind me cannot stop in time and collided onto my car's rear portion. The impact force my car forward and collided onto the front car. I alight and notice that it is a chain collision involving 4 cars. My car's front and rear are damaged and my passengers suffered ~~from~~^{with} injuries.

Declaration

We declare the foregoing particulars are true in every respect.

Kelly 14/01/23 14:30hrs

Policyholder's Signature / Date & Time

Catli 14/01/23 1430hrs

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel




**SINGAPORE
POLICE FORCE**


T/20230114/2111

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

1 of 3

Report No. T/20230114/2111

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/01/2023 23:16	Vide Report No.:	Station Diary No.: 127
--	------------------	---------------------------

Informant's Particulars

Name of Informant: TAN CHEW MENG			Address: 608 ELIAS ROAD #12-178 SINGAPORE 510608	
ID Type / ID No.: NRIC NO / S0025556D			Contact No.:	Mobile: 97709252
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 68	Date of Birth: 31/08/1954	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Retiree			Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/01/2023 12:00	Type of Location: Straight Road
Location: KALLANG PAYA LEBAR EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDJ87A	Car				Slightly Damaged	0
SFF1520G	Car				Slightly Damaged	0
SJE323Z					Slightly Damaged	0
SLK2734C	Car				Seriously Damaged	4


**SINGAPORE
POLICE FORCE**


T/20230114/2111

2 of 3

Report No. T/20230114/2111

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN CHEW MENG	ID No.	S0025556D
Related Vehicle	SLK2734C (Car)	Contact No.	97709252
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	02	Degree of Injury	Slight

Brief Details.

On the 14/01/2023 at about 1200hrs i was driving my vehicle (SLK2734Z) on the 1st lane (most right) at KPE highway tunnel heading towards ECP. I also had 4 other passengers in my vehicle. I saw the vehicle in front of me slowed down as such, i did an emergency brake. After my vehicle successfully slowed down, a white Maserati car bearing a plate number of SJE323Z collided into the rear of my vehicle. That caused a chain collision which involved the cars mentioned above. After the accident, we exchanged particulars and only my vehicle was towed away. Subsequently, we went to Sengkang General Hospital to get ourselves checked and i received 2 days MC and the number of MC days received for my family members who were in the vehicle varies from 2-5 days. The damages suffered to my vehicle were dents on the front and rear of my vehicle.



**SINGAPORE
POLICE FORCE**



T/20230114/2111

3 of 3

Report No. T/20230114/2111

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

G /

SGT 1 MUHAMMAD
NASRULLAH AFIQ BIN
ZULKIFLIE

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

14/01/2023 23:16

Officer In Charge Of Case:

TP / AEIT /
SI ANG YI TING, STEPHANIE
Contact No.: 65476414

Classification Of Case:

NP168

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 556B

Vehicle Details

Vehicle No.: SLK2734C

Vehicle to be Exported: No

Intended Deregistration Date: 26 Jan 2023

Vehicle Make: HONDA

Vehicle Model: SHUTTLE 1.5G A

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: L15B539065

Chassis No.: GK81007748

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$19,413.00

Original Registration Date: 11 Jan 2017

First Registration Date: 11 Jan 2017

Transfer Count: 0

Actual ARF Paid: \$9,413.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 10 Jan 2027

PARF Rebate Amount: \$6,118.00

Intended COE Rebate Details

COE Expiry Date: 10 Jan 2027

COE Category: A - Cap up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$50,101.00

COE Rebate Amount: \$19,824.00

Total Rebate Amount: \$25,942.00

The information contained herein is correct as at 26 Jan 2023

OK

Toyota Alphard
The ultimate family car! Supreme road presence with space for the whole family and much more.

DON'T MISS OUT!

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

BMW X3 XDrive28i M-Sport 2017 Jan, New Road Tax.



Good With Family With Kids,
Reliable Drive, Smooth Driving.
Direct Owner

Think One Automobile

NEW & USED COMMERCIAL VEHICLES

« Back (1 2) Next »

Sort by 20 results/page

21 vehicles



Shuttle

Any Category

Advanced Search

Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Shuttle		Any	Any	2017	Any	Any	Any	Available
	Honda	Shuttle 1.5A G	\$60,388	\$14,060 /yr	10-Jan-2017	1,496 cc	66,500 km	Sedan	Available
1 owner! Low mileage with 06 month warranty! Classy pearl white with black roof, black leather upholstery, superbly well maintained with 15" sports rims, ideal car family with very spacious boot and legroom space! Lowest fuel efficiency car in market! High loan and trade in... This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More Wunder Auto Pte Ltd Posted: 23-Jan-2023									
	Honda	Shuttle 1.5A G	\$61,800	\$14,440 /yr	11-Jan-2017	1,496 cc	72,120 km	Stationwagon	Available
1 owner only, guaranteed non - PHV unit! Low mileage. New road tax. Paintwork like brand new. Enhanced Pioneer audio system. 100% accident free! Huge and spacious boot space and legroom. Very good fuel efficiency of at least 16km/l. Flexible loan scheme available! L... Posted: 09-Jan-2023									
	Honda	Shuttle 1.5A G	\$63,800	\$14,580 /yr	03-Mar-2017	1,496 cc	-	Stationwagon	Available
Beautifully wrapped up in satin yellow wrap. We'll maintained unit. \$0 admin and processing fees for all bank loans. Other loans welcome. Posted: 04-Dec-2022									
	Honda	Shuttle 1.5A G	\$62,800	\$13,800 /yr	15-Apr-2017	1,496 cc	80,108 km	Stationwagon	Available
1 owner! Guaranteed non PHV usage! Elegance silver with black leather upholstery, superbly well maintained with 16" sports rims, original paintwork, ideal car family with very spacious boot and legroom space! Lowest fuel efficiency car in market! High loan and trade in avail... This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More Posted: 16-Jan-2023									
	Toyota launches new ad spot for the Crown The new ad spot showcases the sedan's dynamic presence and styling, designed to make drivers stand out from the crowd. Find out more!								
	Honda	Shuttle Hybrid 1.5A	\$67,800	\$15,470 /yr	17-Apr-2017	1,496 cc	54,000 km	Stationwagon	Available
Fuel Type: Petrol-Electric Rare 1 Owner Shuttle Hybrid! Best Reliability With Excellent Fuel Consumption at 25km/L! Tip-Top Condition With No Touch Up & Repair Require. Low Mileage Clocked, STA Grading Welcome For A Peace Of Mind! Full Loan Available With High/Fast Approval! Bank Loan & PH... SG Car Choice Pte Ltd Posted: 08-Jan-2023									
	Honda	Shuttle 1.5A G	\$61,800	\$13,660 /yr	19-Apr-2017	1,496 cc	68,000 km	Stationwagon	Available
Well maintained, no repairs needed. Accident free. Welcome any 3rd party workshop inspection. Trade in your car are welcome. Bank and in house loan available. Insurance are available too. Viewing by appointment only. Posted: 05-Dec-2022									

Compare