

ASS. R. = V.D. Tanpoh

REF: CS 3/LPC 23000824/Tnp3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Insp. ed Vehicle No: _____
at Work-shop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$550K
IDAC Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS WP PRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGJ82C Yr Regn: 2017 Aug.
Type: M. Car / Motorcycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Bentley Bentayga C.C. 3956
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 33909 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: SJA4E14V2 JCO18714
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: NIL / S/Rim / STD A/Rim or
Tyre Size: F: 285/45R21
R: 4
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 02/02/23 04pm
Survey held at 613
Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
30/03/23	submit prs

Date/Time, File Pass to? ☐ : Preli. Report
1) 30/03/23 ☐ : Final Report
Date/Time, File Return to?
2) _____
Rep. Format: _____
Lump Sum / L.B.K. (?) _____

Days Of Repair: _____
Resurvey No. of Trip: 1
Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)
Survey Fee: _____
Transportation: _____
S + RS. SI _____
Photos _____
Others _____
TOTAL _____