

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGL 512T

at Workshop m/s TAN CHONH

of 911, BUKIT TIMAH RD

Insured: U012

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record) 500

Make of Veh: _____

(Policy Condition)

10am

Remark: The veh had commenced its repair at the time of inspection.

⊕	
N/S	O/S

Bal. or Market Value: 51K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGL 512T Yr Regn: 2016 / Jun

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NISSAN QASHQAI 1.2 DIG c.c 1197

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 41969 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SNPFAJ11U1694378

Gen. Cond: Good Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 21/01/23 D.O.I. 30/01/23

Survey held at TAN CHONH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 23K

We will be advising our principal a cost of repair of \$5,764.94 before excess \$500.00 before GST with 4 days

(red, \$1522.74, 21%)

Date/Time, File Pass to?

: Preli. Report

1) 04/05/23

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

Report Format : _____

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0023/2023
DATE : 27-JAN-2023

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD #02-01
UOI BUILDING
S(068909)
TEL : 62227733/64909318
FAX : 63273869 / 72
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MISS TAY YANLING, DORA (ZHENG YANLING, DORA)
ADDRESS : BLK 202 BUKIT BATOK STREET 21
#12-100
S(650202)
TELEPHONE NO : 97461839

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : DH0M110162371804
VEHICLE NO : SGL512T
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2294428A
CHASSIS NO : SJNFEAJ11U1694378
MILEAGE : 1 KM
DATE IN : 27/01/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 21/01/2023

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 FRT LICENCE PLATE <i>OK</i>	FLP			60.00
2 BUMPER SET FR <i>OK</i>	62022-4EA0H	811.30		
3 GROMMET(\$2.6X2) <i>OK</i>	01281-00111			5.20
4 ENERGY ABSORBER ?	62090-4EA1B	260.40		
5 ARMATURE ASSY-F ?	F2030-4ENMA	898.70		
6 COVER-BUMPER ?	622A0-4EA0A	24.90		
7 GRILLE-RADIATOR ?	62310-4EA1A	624.50		
8 EMBLEM RAD GRIL ?	62890-4EA0A	86.20		
9 LAMP ASSY-RH <i>OK</i>	26010-4EA2A	660.10		
10 CLIP(\$1.4X10) <i>OK</i>	01553-05933	14.00		
11 SUNDRIES <i>OK</i>	NPN			30.00
SUB TOTAL		3380.10	0.00	95.20
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		676.02	0.00	0.00
GRAND TOTAL		2704.08	0.00	95.20
OVERALL TOTAL		2799.28		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
2	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	/
4	ZZ/001	REPAIR RH FR FENDER & HOOD RENEW FR BUMPER	840.00	560
5	ZZ/002	S/PAINT FR BUMPER, RH FR FENDER & HOOD	800.00	750
TOTAL LABOUR CHARGES			1808.00	

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGL512T

TOTAL LABOUR CHARGES	1808.00
TOTAL SPARE PARTS CHARGES	2799.28
GRAND TOTAL	4607.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME : *Pawan - HP 9000068*
SURVEYED DATE : *30/01/23 @ 1010*
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00 *4 days*
LIABILITY : 0.00 *7/P*
REMARKS :
EXCESS: TBA
Repair
Resny before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/01/2023 10:33 (SGT)
Reported by	Both
Date of Accident	21/01/2023 21:27 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BUKIT BATOK EAST AVE 2
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGL512T

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAY YANLING, DORA (ZHENG YANLING, DORA)
NRIC No	SXXXX506G
Email Address	AQUILA_1508@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-97461839
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Qashqai
Variant	NISSAN QASHQAI 1.2
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1198

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Policy Number / Cover Note Number	DH0M110162371804

DRIVER

Name of Driver	TAY YANLING, DORA (ZHENG YANLING, DORA)
NRIC No	SXXXX506G
Date Of Birth	15/08/1981
Occupation	Indoor

Date Of Driving Pass	28/01/2004
Driving experience	19 YEARS
Gender	Female
Mobile Number	(Phone) +65-97461839
Alt. Phone Number	-
Email Address	AQUILA_1508@YAHOO.COM.SG
Address	202 BUKIT BATOK STREET 21
Address complement	12-100
Postcode	650202
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head on collision
Weather Conditions	Clear
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW800G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LOH CHUN HOWE IVAN
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-
	1

SKL512T

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claim process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or dishonesty of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurer or agencies is not an admission of policy liability on the part of the insurance company.
- 5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a long be made available upon appropriate written request.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the online and to copies of this report being made available a/overseas.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the **Personal Information**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **Insurers**), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the **Purposes**).
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.


Wawa 25 Jan 2023

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



Describe Circumstances of the Accident

Accident Location: BUKIT BATOK EAST AVE 2
 Accident Date: 21 Jan 2023 Time: 9 27 am/pm
 Owner Email: aquila-1508@yahoo.com.sg Driver Email: NA

On 21 Jan 2023, I was driving along Bukit Batok East Ave 2 (outside Hillview Resency) and stopped when the traffic light turn red. Once the car was in a stationary mode, I bent down to pick up something that I dropped. Unknowingly, I didn't hold the brake hard enough & the car moved forward & bumped into the car in front.

OTHER VEHICLE NO INVOLVE DETAILS :-

B	Veh No:	SKW8006	Hp:	90075523	Total Pax:	1	Driver Name:	Loh Chun Howe, Lwin
C	Veh No:		Hp:		Total Pax:		Driver Name:	

Declaration

I/We declare the foregoing particulars are true in every respect

Wong 25 JAN 2023
10 25 am

Policyholder's Signature (Date & Time)

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by: [Signature] Witnessing Officer

PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	506G
Vehicle No.:	SGL512T
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2023
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	HRA2294428A
Chassis No.:	SJNFEAJ11U1694378
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,689.00
Original Registration Date:	29 Jun 2016
First Registration Date:	29 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$13,689.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2026
PARF Rebate Amount:	\$3,897.00
COE Expiry Date:	28 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$18,829.00
Total Rebate Amount:	\$27,726.00

The information contained herein is correct as at 31 Jan 2023

OK

Nissan Qashqai 1.2A DIG-T

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price **\$53,800**

Depreciation **\$13,560 /yr**
View models with similar depre

Reg Date 19-Jul-2016
(3yrs 5mths 17days COE left)

Mileage N.A.

Manufactured 2016

Road Tax \$508 /yr

Transmission Auto

Dereg Value \$27,010 as of today (change)

OMV \$18,689

COE \$52,301

ARF \$13,689

Engine Cap 1,197 cc

Power 85.0 kW (113 bhp)

Curb Weight 1,285 kg

No. of Owners 2

Type of Vehicle SUV