

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305543123
REGN NO : SHC2956T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 01.03.2019
DATE/TIME IN : 19.01.2023 13:10
ACCIDENT DATE : 19.01.2023

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2815-G	LAMP ASSY-HEAD LH#	1	2,110.30	20.00	1,688.24	ser /
0002	04-01-0104-3818-G	BRACKET-FR BUMPER SIDE LH	1	35.00	20.00	28.00	? nn
0003	04-01-0104-2534-G	COVER-FR BUMPER#	1	481.10	20.00	384.88	Br /
0004	04-01-0104-2361-G	MOULDING-FRONT BUMPER CTR	1	368.50	20.00	294.80	? nn
0005	04-01-0101-0111-G	BUMPER COVER CLIP	10 L	22.00	20.00	17.60	NEC /
0006	04-01-0104-0632-G	MOULDING-FRONT BUMPER LH	1	93.45	20.00	74.76	? nn

SUB-TOTAL : 2,488.28 2090.72

JOB NATURE

0000	L	PANEL BEAT	400.00	350
0001	SP	SPRAYPAINT CHARGE	300.00	250
0002	17-01	CHECK ALL LIGHTING	50.00	30

SUB-TOTAL : 750.00

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/5

19/1/23

4pm

2720.72

20% = 544.14

= 2176

= 2150