

(06/11/17)

Smf

REF:

ASS. REC. BY:

ASSIGNMENT

Yr Regn: 17/08/2017

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

2

days

Res: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: Sha 583Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Priusc.c. 798Colour Blue yellowA/C: Insured / Std / NI / NASp. Reading 801974T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FNX03561223Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rlm / STD / ARlm orTyre Size: F: 195/65 R15R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 09/1/23D.O.I. 12/1/23 3pmSurvey held at ComfortDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

TOTAL

Date/Time: 10.01.2023 10:51

Page : 1

Team: ARC Repair TP(CFS0)1

JOB CARD Sales Order: 5612322


JC NO.305542225

OWNER IS CITYCAB PTE LTD OWNER NO 7010070 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65551188 (O) (P) DUNT CARD NO.	REGN NO: SHA 58J	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4)10	DATE/TIME IN 01.2023 09:35
	YR OF MANU 17.08.2017	TARGET DATE
	CHASSIS CODE JTDKB3FUX03561223	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 09.01.2023
NATURE: 3P.09.01.23

/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vehicle No.: SHA 58J JU CHINA

Vehicle No.: SHA 58J

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard