

Surveyor:

REF:

CS/LAW 23000857/Tay3

Special Instruction:

ASSIGNMENT (Office)

From (Person): Nazirah Salleh of Legal Solutions Date/Time: 20/1/2023

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor:

Workshop: Xin Yun Auto.

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SMU 6645K

Insured: YN 81378

at Workshop m/s Xin Yun Auto

Tel: 9839 1555 Yi Xin

of

Policy No:

Claim No: AK2/MCS/nzs/1067390.NTUC(mpd)

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25/1/2021

(Client's Record)

2/1/2022

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original days)

Date/Time: Submit Final Fig days (Red \$ / %; Original days)

Date/Time	Action/Instruction
	SMU 6645K - X
	YN 81378 - X
	Survey at: 823A Tampines St 81 Spore 521823
	Multi Storey Carpark
30/1	Yi Xin had arranged the inspection before the email come in.

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :
Salvage Value :
Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

- | | | | |
|--------------|--------------|--------------|----------------|
| 1) Date/Time | File Pass to | 2) Date/Time | File Return to |
| 3) Date/Time | File Pass to | 4) Date/Time | File Return to |
| 5) Date/Time | File Pass to | 6) Date/Time | File Return to |