

REC BY: Tough

REF:

021 HLA 23000 861 / T4y3.

ASSIGNMENT

From: _____ Date: _____
Estimated cost: _____
OD / TP / VS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: \$300
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: \$45K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Veh No: SLB 3715 Z Yr Regn: 2016 / April
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Volkswagen Golf c.c. 1197
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 98192 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WVW EZZAYZEW 186959
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 205/55R16
R: 1 ~
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /
TOYO / YOKO, or _____
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 2/2/23
Survey held at Sing Ann Tee
Des. of Damages: Fri / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report
1) ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: _____
Resurvey No. of Trip: _____

2) _____
Report Form: _____
Lump Sum / Bk: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + RS	\$ _____
Photos	
Others	

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **HL Assurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MP317255	Date of Loss:	13/01/2023
Vehicle Reg. No.:	SLB3715Z	Driveable?	
Driver Age/Info:	54 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN HUI NING PRISCILLA	Contact No:	+6596408012
Driver:	TAN HUI NING PRISCILLA		
Make/Model:	VOLKSWAGEN GOLF, 1.2 TSI G12BZ (A)	Vehicle Reg. Date:	04/04/2016
Vehicle Colour:	GREY	Chassis No:	WVWZZZAUZGW186959
Engine No:	CYV084492		
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER TO SKETCH		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	3,784.00
Miscellaneous Items	0.00
Labour	1,360.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,144.00
+ GST 8.00% (S\$)	411.52
Nett Amount (S\$)	5,555.52

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jan 2023)
Parts: 144 VOLKSWAGEN GOLF 1.2 TSI G12BZ (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLB3715Z)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR LH	0.00	0.00	H- *1,300.00 F
2	1		*REAR DOOR GLASS REGULATOR LH	0.00	0.00	? *260.00 F
3	1		*REAR DOOR GLASS MOTOR LH	0.00	0.00	? *180.00 F
4	1		*RACKER PANEL LH	0.00	0.00	Rx *1,700.00 F
Sub Total (S\$)						3,440.00
+ Margin on L,N Items 10.00% (S\$)						344.00
Total Parts (S\$)						3,784.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK RR FENDER LH,WELD,REMOVE & FIX ON ABOVE PARTS	New 400	500.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New 500	600.00
3	CHECK WIRING	New x	30.00
4	TO TRANSFER REAR DOOR GLASS LH	New 60	80.00
5	TO DIAGNOSE & RESET FAULT CODE	New x	150.00
Gross Labour Cost (S\$)			1,360.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfah 9749549 9/2/23
Not Authorise C1020
EX \$300
1/5 Resurvey after repair
tanfah@lkkauto.com
04 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
subject to final approval from Insurance Company

Acknowledged by Repairer

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	005F

Vehicle Details

Vehicle No.:	SLB3715Z
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jan 2023
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.2 TSI AT 5G12BZ
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	CYV084492
Chassis No.:	WVWZZZAUZGW186959
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$18,208.00
Original Registration Date:	04 Apr 2016
First Registration Date:	04 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$8,208.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Apr 2026
PARF Rebate Amount:	\$5,335.00

Intended COE Rebate Details

COE Expiry Date:	03 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,504.00
COE Rebate Amount:	\$14,594.00
Total Rebate Amount:	\$19,929.00

The information contained herein is correct as at 19 Jan 2023

OK