Our	Job F	Ref No :	305543933			COV	AFORTDELGRO Engineering
	5// 		02.02.23			59 Lo	ortDelGro Engineering Pte Ltd yang Oriva Singapore 508969 3546 8156
	ALIZA	TION FORM				rax. c	3340 8136
	: .		LKK			Fax:	
Attn	FINALIZATION FORM To :		NAZ				
Vehi	cle Re	eg No. Sh			Date	e of Accident :	27.01.23
The	surve	y and estimates	of the repairs of the above-n	nentioned	vehid	e are as follow	s:-
				TOKIO			SLQ5976U
2.	The	finalized amou	nt shall be				
	FINALIZATION FORM To :						
	FINALIZATION FORM To :						
	8 8	-0.0000 -0.000000000	701613743				
			- Sy are repair cost				
	(c.)	Total for Lum	psum repair cost after Less:		20%	/	\$4,050.00
4.	We si 7 wor	hall treat the a king days	bove amount as Correct a	3 nd Confir	med i	orking days. f there is no re e confirm the ealized amount	estimates and
N To	ame el	: JUMANI : 621483	15		Na	gnature: ame : ate :	NAZ 3/2/2023
			,,,				
For Offic	cial U	se Only					
	Ite	em	Amount	Docum Attac Yes o	hed	Confirm By (Signature)	Remarks
1. Renta	l Rate	P/Day		YE	s		
				NC)		
3. Surve	y Fee	8	••••				
LTAS			26.75/2.00	YE	-		
Medical of drive	al Fed er, if a	es (on behalf applicable)					
6 Overru	ın						
Remarks:							

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER: CTPL

Tokio Marine Insurance Singapore Ltd (HQ

musun,

Singapore

PART	ADC	OE	CI	A IRA
PARI	LAKS	UF	CL	MIIVI

Claim Type:

THIRD PARTY

Ref. No:

Policy No:

Date of Loss:

27/01/2023

Vehicle Reg. No.: Party At Fault:

SHA1790X UNKNOWN Driveable?

YES

Make/Model:

HYUNDAI 140, 1.7 D CRDI (A)

Vehicle Reg. Date:

22/12/2016

Vehicle Colour:

BLUE

Gen Condition:

GOOD

Engine No:

D4FDGU712700

Chassis No:

KMHLB41UMHU097269

Odometer:

Paint Type: List Item Discount:

20.00 %

0 KM

Total Loss?

NO

Est. Duration of Repair

(day)

5

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
Parts		4,210.64
Miscellaneous Items		11.00
Labour		1,600.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	5,821.64
	+ GST 8.00% (S\$)	465.73
	Nett Amount (S\$)	6,287.37

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 30 Jan 2023)

Parts:

143

HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA1790X/30/01/2023 09:58

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

	Qty Part No.	Particulars	%Disc	%Depr	Amount
	3	*FRT BUMPER ASSY	20.00	0.00	⟨¢9/*1,052.20 FL
1	1	*FRT BUMPER GRILLE LH	20.00	0.00	CRA /*187.20 FL
2	1		20.00	0.00	NE. /*22.00 FL
3	10	*FRT BUMPER CLIPS *HEADLAMP ASSY LH	20.00	0.00	
4	1		20.00	0.00	CA 1,480.00 FL
5	1	*RADIATOR GRILLE	20.00	0.00	DD /*663.00 FL
6	1	*FRT FENDER LH	20.00		SVL X? *174.90 FL
7	1	*FRT FENDER SHIELD LH	20.00	0.00	SVLX? *126.20 FL
8	1	*FRT FENDER AIR DUCT LH	20.00		SVC X ? *44.80 FI
9 10	1	*FRT BUMPER SIDE BRACKET LH *ADVERTISEMENT - FRONT FENDER	0.00		NEC /*100.00 F
(m) (m)	nchise part. L=ListItem				5,238.30
		Sub Total (S\$)			-
		- List Item Discount on L Items (S\$)			1,027.66
		Total Parts (S\$)			4,210.64

ComfortDelGro Engineering Pte Ltd/SHA1790X/30/01/2023 09:58. Not valid without Reference section. Generated using Merimen e-Claims IEAS

timates on Miscellaneous Itoms

	No Qty Particulars	
1	Miscellaneous Items	

1 1	1	OD/TP Case (Insurer)		11.00		
			Sub Total (S\$)		11.00	

L-ct	Ima	20	On	1 2	DOLLE
Lou	IIIIa	ıcs	OH	Lai	bour

No	Particulars	Lab.Type		Amount
Lab	our Items			
1	PANEL BEATING	New .	560	900.00
2	SPRAYPAINT	New	500	600.00
3	CHECK WIRING	New	30	50.00
4	TUFF KOTE	New	40	50.00
		Gross Labour Cost (S\$)		1,600.00

ComfortDelGro Engineering Pte Ltd/SHA1790X/30/01/2023 09:58. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NAZ LKK 31/1/2023 1610 LU 3 DAYS CHE CK HEM PHOTOS AFTEL REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Amount