COMFORTDELGRO Our Job Ref No : 305543933 Date ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 02.02.23 FINALIZATION FORM To LKK Fax: Attn : Mr NAZ Vehicle Reg No. SHA1790X Date of Accident: 27.01.23 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-1. The repair job shall bill 703A TOKIO SLQ5976U 2. The finalized amount shall be: (a) Spare Parts after List discount (b) Labour Charges Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% \$4,050.00 Final Lumpsum Repair cost 3. Estimated normal period for repairs: 3 working days. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature: Signature: Name : JUMANI NAZ Name 3/2/2023 Tel : 62148315 Date Fax : 65468156 For Official Use Only Document Confirm By Item Amount Attached Remarks (Signature) Yes or No 1. Rental Rate P/Day YES 2. Loss of Income Paid NO Survey Fees ---.... LTA Search Fee 26.75/2.00 YES 5. Medical Fees (on behalf of driver, if applicable) Overrun

Remarks: