



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23000881/Dny3m4	
			Date: 27/02/2023	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 1329R	Veh. Inspected	SGM 51B
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/01/23/2063	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	30/01/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	CITROEN DS5	c.c	1560
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	VF7KFBHGTGS505028	Colour	GREY
	Odometer	122323 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	KAPSEN	5 mm
	L/H Front Tyre	225/50 R17	KAPSEN	5 mm
	R/H Rear Tyre	225/50 R17	KAPSEN	5 mm
	L/H Rear Tyre	225/50 R17	KAPSEN	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	26/01/2023	Inspection Date	31/01/2023
	Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #02-16 AMK AUTOPOINT SINGAPORE 568047		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	