

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI23000884/Uqy3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dat	e: 14/02/2023	
			Cod	de: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMG 3324E	Veh. Inspected	SLC 1325Z	
	Policy No.	P10487730R02	Coverage (\$)	0.00	
	Claim No.	C10020127 /JM	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	27/01/2023	
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 3 (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JM6BM42A8G0336689	Colour	WHITE	
	Odometer	113562 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/45 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	215/45 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	215/45 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	215/45 R17	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	24/01/2023	Inspection Date	06/02/2023	
	Survey held at	TLM AUTOMOBILE PTE LTD			
		1 DEFU LANE 6, DEFU INDUSTRIAL PARK A, SINGAPORE 539365			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	1= /	·	Days of Repair		

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: