

(08/11/13)

we

ASS. REC. BY:

REF:

CC4/A1823000922/Rp23

C
4380**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SNF 69820at Workshop m/s MOTORWAYof 4, JUN HUNT

Insured:

M/S

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

117K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNF 69820Yr Regn: 2022 / Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SEANHYONH TIVOLI 1-60C.C. 1597

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

24956

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KPT 30A1W8LP 318095Gen. Cond: Good / Fail / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

RYAN 2

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/01/23

D.O.I.

30/01/23

Survey held at

MOTORWAYDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 48K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

Motorway Car Care Centre Pte Ltd

1094 Lower Delta Road Motorway Building Singapore 169805

Tel: 6468-2200 fax: 6278-5535

GST:20000606-K RCB NO: 20000606-K

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- Display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Estimate No: QT2310911

Date: Date: 27/1/2023

Policy No:

Veh Reg No: SNF6982D

Make/Model: SSANGYONG TIVOLI

1.6D STD 6AT 2WD ABS

Chassis No: KPT30A1USLP318095

Engine No: 67391002094988

Reg.Date: 16/06/2022

M/S: ALLIANZ INSURANCE SINGAPORE PTE LTD

75 BRAS BASAH ROAD

SINGAPORE 189557

TEL: -

ATTN: MOTOR CLAIM DEPARTMENT

Your Ref No: SNF6982D

Claim Type: Third Party

Accident Date: 21/01/2023

TP Veh Reg No: SMP333B

LABOUR \$400 // SPRAY PAINT // \$450

Rasul
Hy 90010018
6 days
43
30/01/23 @ 1140
Repair after repair

Estimate Repair Cost to Vehicle No :

NO.	Description	Quantity		List Price	Amount
				\$\$	\$\$
1	FRONT FENDER <i>X</i>	RH	1pc	794.76	794.76
2	FRONT DOOR <i>4</i>	RH	1pc	1800.00	1800.00
3	REAR DOOR <i>4</i>	RH	1pc	1800.00	1800.00
4	REAR DOOR UPPER HINGE <i>X</i>	RH	1pc	55.00	55.00
5	REAR DOOR LOWER HINGE <i>?</i>	RH	1pc	55.00	55.00
6	REAR DOOR CHECKER <i>X</i>	RH	1pc	110.00	110.00
7	REAR FENDER WHEEL ARCH MOULDING <i>see</i>	RH	1pc	135.63	135.63
8	SIDE SKIRT <i>see</i>	RH	1pc	283.365	283.365
				TOTAL	5033.76
				LESS 10%	503.3755
				TOTAL	4530.38

	<u>SPECIAL NETTS</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	REAR FENDER WHEEL ARCH MOULDING CLIPS <i>see</i>	1pc	40.00	40.00 ✓
2	SIDE SKIRT CLIPS <i>see</i>	1pc	40.00	40.00 ✓
			TOTAL	80.00

LABOUR CHARGE

1	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.	\$	1,200.00 <i>900</i>
2	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	\$	2,250.00 <i>1200</i>
3	TRANSFER DOOR MECHANISM (X2 DOORS)	\$	360.00 <i>120</i>
4	TO CARRY OUT DIAGNOSTIC TEST	\$	450.00 <i>150</i>
TOTAL		\$	4,260.00
TOTAL PARTS		\$	4,610.38
GRAND TOTAL		\$	8,870.38

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	438D
Vehicle Details	
Vehicle No.:	SNF6982D
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2023
Vehicle Make:	SSANGYONG
Vehicle Model:	TIVOLI 1.6D STD 6AT 2WD ABS E6 FL
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	67391002094988
Chassis No.:	KPT30A1USLP318095
Maximum Power Output:	96.5 kW (129 bhp)
Open Market Value:	\$19,893.00
Original Registration Date:	16 Jun 2022
First Registration Date:	16 Jun 2022
Transfer Count:	0
Actual ARF Paid:	\$19,893.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jun 2032
PARF Rebate Amount:	\$14,919.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jun 2032
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,599.00
COE Rebate Amount:	\$53,999.00
Total Rebate Amount:	\$68,918.00

Ssangyong Tivoli Diesel 1.6A Standard

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price **\$98,800** (2.98% loan with \$500 cash back.) [Get Pre-approved Loan.](#)

Depreciation ⓘ **\$11,470 /yr**
[View models with similar depre](#)

Reg Date **30-Oct-2020**
(7yrs 8mths 28days COE left)

Mileage **50,789 km (22.5k /yr)**

Manufactured ⓘ **2020**

Road Tax ⓘ **\$1,182 /yr**

Transmission **Auto**

Dereg Value ⓘ **\$43,794 as of today (change)**

Fuel Type **Diesel**
(Euro 5 Engine and Above)

COE ⓘ **\$37,334**

OMV ⓘ **\$19,824**

Engine Cap **1,597 cc**

ARF ⓘ **\$19,824**

Curb Weight ⓘ **1,425 kg**

Power **96.5 kW (129 bhp)**