

 Service Requests Messages Claims

Service Request Details

Claim	S3M04II2
Reference	CS/ASM23000923/Kqp3m4 
Loss Date	27 January 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	30 Jan 2023 9:15:49 AM
Request Date	31 January 2023
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information	
Incident	SMD9631U
Vehicle	
Registration #	
Make	TPVD
Model	Honda
Service Address	
, , ,	
Primary Contact/Insured	

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

HO Winnie

winnie.ho@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRI TP PDF.pdf	Other	Other	do not reply	
 HSB-LKKInvoice-	Invoice	Surveyor/ Assessor	LKK AUTO CONSULTANTS PTE	20 February

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
AC2300962.pdf.pdf		expense	LTD (TP)	2023
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2023
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2023
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	20 February 2023
 SMD 9631U-IA.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 February 2023
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	31 January 2023
 SJ0G231S0005-SHD7124P.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	30 January 2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	30 January 2023
 SMD9631U TP TGIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	30 January 2023