

Eng/No: REF: ASS. REC. BY: Kenneth

REF: AIS/23000930/KP

ASSIGNMENT

Veh No: SKP 9899A Yr Regn: 03, 18
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia ES250 C.G. 2494

Colour: M. L. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 79578 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTHBJIGG902106593

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 3/1/23

Survey held at 2/12/22

Rear


R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 1/2/2023

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$125k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

14/7/23 Final fig \$9207.02 confirmed by email (Red 6930.98, 42%)

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Transportation

☐ S - RS. SI

☐ F. 1/16

☐ Others

Date/Time, File Return to?

26/7/23-typist

Report Format: Merimen

Imp Sum + I.B.I. (\$9207.02

Not Authorised
 Resurvey B4 paint
 Ex 3700h

MODEL: LEXUS ES250

VEHICLE NO: SKP9899A
CHASSIS NO: JTHBJ1GG902106593

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)	
<u>PARTS (LIST ITEMS)</u>		
FRONT BUMPER	BH1cm \$	1,000.00 ✓
FRONT BUMPER RETAINER RHS	\$ D.T	70.00 ✓
FOG LAMP COVER RHS	\$ M	150.00 ✓
HEADLAMP RHS	Cur \$	6,200.00 ✓
HEADLAMP BRACKET RHS	\$	80.00 7
FRONT FENDER RHS	n \$	1,450.00 X
FRONT REINFORCEMENT	\$	600.00 7
SUPPORT PANEL	n \$	1,600.00 X
WIPER TANK	\$	320.00 7
Front grille assy 1200 CRH		
Front grille chrome garnish 1150 CM ✓		
	10%	\$ 11,470.00
		\$ 1,147.00
		\$ 10,323.00
<u>SPECIAL NETT ITEMS</u>		
FRONT BUMPER CLIPS 1 SET	n \$	100.00 ✓
FRONT FENDER INNER SHIELD CLIPS 1 SET	m \$	100.00 X
Total	\$ 200.00	
TOTAL PARTS		\$ 10,523.00

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	
1	<u>LABOUR</u> To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00	400
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	20
4	To provide anti-rust treatment on affected areas	\$ 100.00	X
5	Dignostic Check	\$ 100.00	7
	Labour Total :	\$ 3,500.00	
	TOTAL (PARTS & LABOUR):	\$ 14,023.00	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/12/2022 12:38 (SGT)
Reported by	Driver
Date of Accident	02/12/2022 13:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	HOUGANG AVE 10 - HOUGANG MALL CP
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP9899A
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIM PENG CHUAN
NRIC No	S6830363Z
Email Address	KARINTSL@GMAIL.COM
Mobile Phone No	(Phone) +65-96612336
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Lexus
Model	Es250
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2494

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	-

DRIVER

Name of Driver	TAN SUAN LIAN KARIN
NRIC No	S7123581E
Date Of Birth	14/07/1971
Occupation	Indoor

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Karin

10:00 am
3/12/2022

Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

A. SKP9899A

B. unknown
vehicle nos.



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

363Z

Vehicle Details

Vehicle No.:

SKP9899A

Vehicle to be Exported:

Yes

Intended Deregistration Date:

01 Feb 2023

Vehicle Make:

TOYOTA

Vehicle Model:

LEXUS ES250 LUXURY A/T S/R

Primary Colour:

Silver

Manufacturing Year:

2017

Engine No.:

2ARF518203

Chassis No.:

JTHBJ1GG902106593

Maximum Power Output:

135.0 kW (181 bhp)

Open Market Value:

\$40,888.00

Original Registration Date:

15 Mar 2018

First Registration Date:

15 Mar 2018

Transfer Count:

0

Actual ARF Paid:

\$49,244.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

14 Mar 2028

PARF Rebate Amount:

\$36,933.00

Intended COE Rebate Details

COE Expiry Date:

14 Mar 2028

COE Category:

E - Open - all except motorcycle

COE Period(Years):

10

QP Paid:

\$38,801.00

COE Rebate Amount:

\$19,859.00

Total Rebate Amount:

\$56,792.00

The information contained herein is correct as at 01 Feb 2023

OK